

JAN 19 2001

2000 REMONUMENTATION

Re-Non. Liber 2, Page 74

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Huron</u> (County)	Located in:	Corner Code #
1. Public Land Survey Sand Beach	T16N R16E	A-12
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

STATE OF MICHIGAN
HURON COUNTY
RECORDED

20 SEP 2000 2:05 PM

FRANCES L. HOLDWICK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Charles S. Getz, in a field survey on July 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6	5										
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

- A. Description of original monument and accessories and/or subsequent restoration:
- A-12 1834 G.L.O., H. Parke D.S. County Road Commission Records - NONE
Set quarter section post
Elm 6", S47°W, 38 Links Recorded Surveys - NONE
B. Ash 6", N 7½°W, 15½ Links
Unrecorded Surveys - NONE
L.C.R.C. - NONE

County Surveyor Records - NONE

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-12
W 1/4 Cor, Section 31, T16N-R16E
Found no evidence of original corner position
Re-established corner position by proportionate measure from G.L.O. Notes, between A-11 and A-13 as best evidence of original corner position for A-12.
(On Edwards Road)

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-12
W 1/4 Cor, Section 31, T16N-R16E
Set 1/2" Re-Rod
S80°W 41.6' to West End of 9' Culvert
S80°E 19.0' to East End of 9' Culvert
S50°W 52.2' to Nail in Top of Wood Post
West 8' to Centerline of Gravel Road
North 2617.20' to NW Cor, Sec 31, T16N-R16E
South 2617.20' to SW Cor, Sec 31, T16N-R16E



Signed by Charles S. Getz

Date July 23, 2000

Surveyor's Michigan License No. 25843

PEER GROUP APPROVED AT MEETING
HELD September 18, 2000. RLB