For corners in

## LIBER 3 PAGE 188

RECORDED

## HILLSDALE COUNTY REMONUMENTATION CORNER HILLSDALE CO. MICH. LAND CORNER RECORDATION CERTIFICATE 97 SEP 22 PM 12 19 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			Abmasmalla. ()
HILLSDALE Code #	Located In:	Corner	George Vangondt
(County) MOSCOW TWP.	TEODOM		REMONUMENTATIO!
Public Land Survey	T <u>5 S</u> R <u>2 W F</u> T R T R	<u>-9</u>	OCT 1 7 1997
	TR		an an a set a territoria e f
2. Property Controlling S_ in Section S_	TR		COMMISSION Register of Deeds Stamp & File Number
3. Miscellaneous S_ Property in Sec. S_	TR		
4. Lot No, Recorde	od Plat		ABCDEFGHIJKLM
5. Private Claims			2 6 5 4 3 2 1
			3
I, EDWARD W. REED	in a field survey on	JUILY 25 19 97 do	4 7 8 9 10 11 12
hereby state that under requireme	nts of P.A. 74, Michigan P.A. of	1970, the corner points	5 6 18 17 16 15 14 13
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior,			7 7
Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of			8 19 20 21 22 23 24
Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,			9
recovered, found as expressed below	r.		10 30 29 28 27 26 25
NOTE: Not more than 2 corners on this certificate.	i, all in the same town and range	e, may be recorded	11
			13
A. Description of original monument and accessories and/or subsequent restoration: QUARTER CORNER FOR SECTIONS 21 & 28, MOSCOW TWP. NO OLD INFORMATION 1984: JERRY WILCOX, SURVEYOR - SET IRON ROD BY SINGLE PROPORTION EAST AND WEST. RECORDED IN LCRC LIBER 2, PAGE 67			
B. Description of corner evider	nce found and/or method applic	ed in restoring or reestablis	hing corner:
FOUND POINTED STONE AI ALSO FOUND WILCOX IROI ACCEPTED STONE AS ORK	N 1.8 ' SOUTH & 0.6' WEST		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
			NG ROAD REPAVING PROJECT POSITION OF THE ORIGINAL
IN LINE WITH FENCELINE R ROUND WOOD ANCHOR PO CENTER OF 40" OAK, SOUT FACE OF ROUND WOOD AN	OST, NORTH 45.00' H 44.2' NCHOR POST, S 20W 42.9'	A separate of the second of th	
CENTER OF 50" COTTONWAS	JUD, SOUE 711.6		Date JULY 25 , 1997
EDWARD W. RE	FD	AVERED AVERED	
Surveyor's Michigan License		LAKE BENEVEYOR	
Carveyor a michigan License	.40	NO.	

MAY 14,1975

JAN. 28, 1971

FORM (IPPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS REVISED

REVISED JAN, 198 REVISED OCT., 199