

FEB 2 1996

IOSCO COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

95-27

STATE OF MICHIGAN
IOSCO COUNTY
FILED

12 DEC 95 2:28 P.M.

BONITA K. COYLE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in

IOSCO

(County)

Located In:

Corner Code #

No. 5

1. Public Land Survey

T23NR 9E

H-3 TO I-3 05

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, WILLIAM E. WOODS in a field survey on 11-2-, 19 95 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1843: ORIGINAL SURVEY

59.65 LKS. SET MEANDER POST. NO TREES

ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 10-31-95

James H. Granger

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1948: SUBDIVISION

MEADS LANDING L.6 P.1

SHOW'S SECTION CORNERS TO THE WEST AND WHAT
APPEARS TO BE SECTION LINE.

1993: SURVEY

SHOW'S SECTION LINE INTERSECTS EASTERLY RIGHT
OF WAY ON CORNER BETWEEN PARCELS I AND J.

EXTEND SECTION LINE AS ESTABLISHED BY R.L.
MILLER, EAST TO LAKE HURON. SET MEANDER CORNER
501.2 EAST OF US-23 RIGHT OF WAY.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995: REMONUMENTATION WILLIAM E. WOODS P.S. 25882

SET 5/8" X 30" REROD WITH ALUMINUM CAP.

4" WHITE ASH N26°W 29.16

6" TWIN POPLAR S80°E 9.06

7" TWIN POPLAR S18°E 55.72

4" WHITE ASH S02°E 27.66

END OF CHAIN LINK FENCE S10°E
119.10

501.2 EAST OF CORNER MONUMENT ON US-23 RIGHT OF WAY.
DISTANCE TO LAKE HURON EAST 163.0

Signed by *William E. Woods*

Date 12-8-95

Surveyor's Michigan License No. 25882

