

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 12 T 43N R 32W	5
	S 12 T 43N R 32W	13
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 5 03/13/13  
13 03/18/13 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 12) North 1/16 corner, Section 12. Not previously monumented.

(13-Sec. 12) Southeast 1/16 corner, Section 12. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 12) Established the position for the corner midway and on a straight line between Center of  
Section 12 1330.67' south and Quarter corner 1330.67' north.

(13-Sec. 12) Established the position for the corner at the intersection of straight lines  
connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx32" I.pipe.  
Set measuring nail with MDNR tag in the side of:  
3" Ironwood N53°E 25.3' mrkd "1/16S BT"  
5" Sugar N75°E 18.45' do  
7" Sugar S86°W 12.55' do  
7" Sugar N56°W 10.7' do  
Set sq'd cedar post adjacent.  
E= 7903198.914 N= 151734.620

(13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" Maple N05°E 4.2' mrkd "1/16S BT"  
8" Sugar S65°E 22.35' do  
5" Sugar S23°W 22.0' do  
8" W.Birch N74°W 8.85' do  
Set sq'd cedar post adjacent.  
E= 7903584.731 N= 150917.496

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.635 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/22/2013

For the Michigan Department of Natural Resources, Forest Resources Division

