

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 32 T 44N R 32W	D12
	S 32 T 44N R 32W	8
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 8 10/05/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D12) Center of Section 32. Not established in the original survey.

(8-Sec. 32) West 1/16 corner, Section 32. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D12) Established the corner at the intersection of a straight line connecting the North and South
1/4 corners of Section 32 with a straight line passing through the West 1/4 corner and having a
bearing which is the mean bearing of the North and South lines of Section 32.

(8-Sec. 32) Established the corner midway and on a straight line between Quarter corner 1316.87' west
and Center of Section 1316.87' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Cedar N44E 56.9' mrkd "C1/4 BT"
7" Y.Birch East 36.3' do
9" Balsam S03W 10.4' do
11" Y.Birch N43W 28.8' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
11" W.Birch S75E 28.7' mrkd "1/16S BT"
15" Maple S34E 19.6' do
3" Maple S88W 21.2' do
9" Hemlock N65W 17.5' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/04/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

