

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located in:	Corner Code #
1. Public Land Survey	T 44N R 34W	B.C-3 (004)
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:04
L.C. Records: L.S. F. 255
Robert L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

West Meander Corner between Sections 6 and 7, T44N, R34W, West bank of Net River

I, Gary L. Pisoni, in a field survey on April 4, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 18, 1851 by Guy H. Carleton U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Fir	6"	S 53° W	13 links (8.58 feet)
Cedar	6"	N 54° W	13 links (8.58 feet)

On 8/25/76, Arthur O. Enger RLS DNR restored the meander corner position from the remains of the original cedar bearing tree and set a 1" diameter by 36" long iron pipe with a 3 3/4" diameter aluminum cap stamped as follows: T44N R34W, M.C., S-6, S-7, 8/25/76, RLS 13581 and recorded in Liber 1, Page 520 of LC records.

1976 Bearing Trees:

White Spruce	10"	S 27° W	40.5 feet
White Spruce	13"	N 28° W	85.2 feet

PEER GROUP APPROVED

Iron Gary L. Pisoni 11-30-2000
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 4/4/2000, found the above described monument and the following bearing trees:

White Spruce	14"	S 28°W	40.93 feet
White Spruce	16"	N 28°W	85.55 feet

Monument is 12" above ground surface and 10 feet from waters edge.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

White Spruce	5"	S 23°E	13.32 feet
Balsam	7"	N 15°W	9.87 feet
Steel sign post		West	0.65 feet

00-023

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 20, 1971

LIBER 8 PAGE 255

