

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

60 DEC -8 PM 12:59

L.C. Records: L. S. P. 236

Gary L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

	(Iron County)	Located in:	Corner Code #
1. Public Land Survey	T 44N R 34W	A-5	
	T 44N R 35W	M-5	
	T R		
	T R		
2. Property Controlling	S T R		
in Section	S T R		
3. Miscellaneous	S T R		
Property in Sec.	S T R		

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Section Corner to Sections 12 and 13, T44N, R35W
Section Corner to Sections 7 and 18, T44N, R34W

I, Gary L. Pisoni, in a field survey on March 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 15, 1846 by William A. Burt, U.S. Deputy Surveyor.
Original Corner; Ironwood Post

Original Bearing Trees:

Sugar	18"	S 15° E	11 links (7.26 feet)
Sugar	16"	N 32° W	24 links (15.84 feet)

In August, 1851, Guy H. Carleton, U.S. Deputy Surveyor established the following new bearing trees:

Sugar	20"	S 65° W	36 links (23.76 feet)
Yellow Birch	10"	N 70° E	14 links (9.24 feet)

On May 30, 1973 Donald D. Lappala RLS USFS restored the section corner position from the stump hole remains of the above bearing trees and set a 2" diameter by 5' long concrete filled iron pipe with a 3" diameter bronze tablet stamped as follows: T44N, R35W, R34W, S-12, S-7, S-13, S18, 1973, RLS 12585 recorded in Liber 3, Page 40 of LC records.

1973 Bearing Trees:

Sugar Maple	7"	N 65° E	30.9 feet
Sugar Maple	7"	S 18° W	13.6 feet
Sugar Maple	10"	S 82° W	22.3 feet
Steel sign post		S 88° W	1.8 feet

PEER GROUP APPROVED

Gary L. Pisoni 11-30-2000
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 3/18/2000, found monument as described above and the following bearing trees:

Sugar Maple	8"	N 69° E	30.69 feet
Steel sign post		N 85° W	1.85 feet

Found existing bearing trees established by the U.S.F.S.

Sugar Maple	11"	N 37° W	34.46 feet
Sugar Maple	7"	N 04° W	31.87 feet
Sugar Maple	12"	N 51° E	11.67 feet

Monument is 24" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

00-004

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995