

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 45 N. R. 34 E. XX W.	E8
2. PROPERTY CONTROLLING IN SECTION 20	T. 45 N. R. 34 E. XX W.	14a
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19 , established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner E8: Wood post	(Not found. No subsequent monuments found)
Maple 6 N32E 31	(" " " " accessories found)
Fir 8 S 3W 29	(" " " " " ")
Corner 14a: Wood post	(Not found. No subsequent monuments found.)
W. Birch 8 N17E 22½	(" " " " accessories ")
W. Birch 7 N 9W 33	(" " " " " ")

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner E8: Re-established 8/20/73 in accordance with examiner's notes of 1854 by A. B. Woods, D.S., who found that this corner was not on line between the sec. corners N & S of it, as reportedly established in the 1851 subdivision. As now set, this corner bears S1°12'W 40.006 ch. from Sec. Cor. 16, 17, 20 & 21 and N 0°30'W 40.004 ch. from Sec. Cor. 20, 21, 28, & 29.

Corner 14a: Re-established 8/26/74 on true sec. line on N. bank of a wide area of Net River, 9.098 ch. S of 1/4 cor. and 30.902 ch. N of Sec. Cor. Set inshore for protection from spring run-off high water, about 10 ft. from water's edge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner E8: 1" I.D. x 35" iron pipe with 3½" aluminum cap.
W. Spruce 11 N31½°W (mag.) 44.2 ft. "1/4S, NBT"
W. Spruce 14 S41°W (mag.) 62.1 ft. "1/4S, NBT"

Corner 14a: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
W. Birch 12 N28°E (mag.) 73.1 ft. "M.C., NBT"
B. Ash 8 N 2°W (mag.) 34.9 ft. "M.C., NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE May 22, 1975

Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

