## LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkos	(i Field Survey Da	ate: September 6, 2016	
For corner(s) in:lron	County A	BCDEFGH	I J K L M.
Original Public Land Survey Corner           a. S         T         46N         R         32W           b. S         T         46N         R         32W           S         T         R	Corner Code 2  F07 (GCDB 340400) 3  D09 (GCDB 240300) 4  5	7 8 9 10 18 17 16 15 19 20 21 22	2 - 1 2 3 3 4 5 5 6 7 23 - 24 8
S TR		30 29 28 27 31 32 33 34	11
Part A. Corner History	13 A	BCDEFGH	1 J K L M

- a.) Quarter corner common to Sections 16 and 21. 1852 Established by Francis Houck, U.S. Deputy, midway and on the Section line between Section corners 40.00 chains east and west. Set post. Fir 10" NO5°W 22 links, Sugar 12" S12°E 16 links. Found no subsequent record.
- b.) Quarter corner common to Sections 20 and 29. 1852 Established by Francis Houck, U.S. Deputy, midway and on the Section line between Section corners 39.79 chains east and west. Set post. Sugar 16" S33°W 45 links, Sugar 18" N46°E 35 links. Northern Paper Mills records: 1931 - Buell & Ellison found 16" Map. B.T. N46°E 35. Set post. Old stump mound S22°W 12 links. [note-previous statement does not seem to make sense -ss] 1950 - D.Buell & Peryam Found sq'd Maple. 1953 - Wickman & Peryam Found sq'd Maple, old post down & intersection of old lines. No trace of B.T.s Set pipe at old post. Sugar 16" S22°W 12 links, Sugar 8" N73°E 51 links.

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

- a.) The original post and accessories were not recovered. At a position consistent with the original record, I found a 2"x2" heavy angle iron, firmly set, projecting 2' above ground, with nearby trees blazed and metal location poster indicating the corner. I accepted the angle iron as the best available evidence of the position of the original corner.
- b.) Found the 1953 monument at record bearing and distance from the 1953 witnesses. The Sugar SW is in good condition with overgrown blazes and location poster. The Sugar NE is dead and down. The top portion of the monument is bent, but the bottom section is straight and plumb. Accepted the position as the best available evidence of the position of the original corner. Removed the 1953 monument and replaced it with a new monument as described below.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

(3)		
a.) Found 2"x2" angle iron.  Set measuring nail with MDNR tag in the side of:  6" Sugar N05°E 4.3' mrkd "1/4S NBT" with L.P.  10" Sugar N85°E 6.95' do  12" Sugar S28°E 12.15' do  9" Sugar S14°W 11.3' do  E= 7898833.289 N= 177926.504	b.) Set 1"IDx28" I.pipe with 2" a Set measuring nail with MDNR tag 24" Sugar S29°W 8.2' old blazes 11" Sugar N21°E 20.1' mrks 11" Sugar S50°E 11.35' 12" Sugar N19°W 23.2' Squared a 2" Y.Birch 1 ft. E'ly. E= 7897206.955 N= 176347.418	in the side of: (1953 NBT) d "1/4S NBT" do do
Bearings are magnetic. Coordinates are MCSB3, NADR Coordinate Reference: MDNR Network control "BONE",	a 1"ID I.pipe	STEPHAN J. TO SZYSZKOSKI

PROFESSIONAL SURVEYOR

PESSION

10/13/2016

Professional Surveyor's License No.: Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908