

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Iron (County)	Located In:	Corner Code #
1. Public Land Survey		T 46N R 35W	G.H-11
		T R	(004)
		T R	
		T R	
2. Property Controlling in Section	S	T R	
	S	T R	
3. Miscellaneous Property in Sec.	S	T R	
	S	T R	

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:04

L.C. Records: L.S. P. 260

*Robert J. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

West Meander Corner Between Sections 27 and 34, T46N, R35W  
West shore of Perch Lake

I, Gary L. Pisoni, in a field survey on September 12, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

#### A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in 1851 by Harvey Mellen, U.S. Deputy Surveyor.  
Original Meander Corner; 20" White Pine  
Original Bearing Tree:

Cedar	9"	S 25° W	9 links (5.94 feet)
-------	----	---------	---------------------

On 5/21/67, Donald D. Lappala RLS USFS restored the meander corner from the remains of the original meander corner and bearing tree. Set a 2" diameter by 5' long iron pipe with a 3" bronze tablet stamped as follows: T46N, R35W, M.C. S-27, S-34, 1967, RLS 12585, recorded in Liber 3, Page 209 of LC records.

1967 Bearing Trees:

Cedar	10"	N 65° W	43.8 feet
Cedar	8"	S 80° W	66.4 feet
Cedar	10"	S 33° W	51.4 feet

PEER GROUP APPROVED

*Iron County Peer Group* 11-30-2000  
COUNTY REPRESENTATIVE

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found cedar bearing tree lying on ground. No scribing visible.

On 9/12/2000, found the above described monument and the following bearing tree:  
Cedar 14" N 67°W 44.01 feet

Monument is 24" above ground surface and 6' from waters edge.

Corner record research on file with County Representative.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Balsam	7"	S 01°E	8.90 feet
Balsam	10"	S 64°W	3.40 feet
Steel sign post		S 30°W	3.6 feet

00-028

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 28, 1971  
27 REVISED MAY 24, 1975  
REVISED OCT 1, 1983  
REVISED OCT 1, 1995

