

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970

For corners in

IRON

(county)

Located in:

Corner Code#

**BATES TOWNSHIP**

T 46 N, R 35 W

E-12 (W 1/4 SEC.33)

1. Public Land Survey

2. Property controlling  
in Section

3. Miscellaneous  
Property in Sec.

S

S

S

S

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -4 AM 10:09

L.C. Records: L.S.P. 189

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

**1/4 CORNER COMMON TO SECTIONS 32 AND 33 T 46 N, R 35 W**

I, STEVEN R. APPLEKAMP in a field survey on NOVEMBER 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by decree of a Court of law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

#### A. Description of original monument and accessories and/or subsequent restoration:

ORIGINAL CORNER ESTABLISHED BY HARVEY MELLEN, U.S. DEPUTY SURVEYOR ON JUNE 12, 1851.

ORIGINAL BEARING TREES:	Y-BIRCH 6" S 47°E 14 LINKS	Y-BIRCH 7" N 67°W 13 LINKS
-------------------------	-------------------------------------	-------------------------------------

1968 DONALD D. LAPPALA P.S. 12585 RESTORED CORNER FROM FOUND EVIDENCE WHICH INCLUDED REMAINS OF ORIGINAL BEARING TREES. HE SET A 2" I.D. BY 5 FEET LONG GALVANIZED IRON PIPE WITH 3" BRONZE TABLET STAMPED AS FOLLOWS: T.46N., R.35W.; 1/4, S-32, S-33; R.L.S. 12585; 1968. RECORDED IN IRON COUNTY L.C. RECORDS. HE MADE THE FOLLOWING BEARING TREES:

CEDAR 12" N 49°W 62.3'	CEDAR 12" N 20°W 68.8'	CEDAR 10" S 65°E 71.6'
---------------------------------	---------------------------------	---------------------------------

PEER GROUP APPROVED

Iron County L. Rep. 11-30-2000  
COUNTY REPRESENTATIVE

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND CORNER IN GOOD CONDITION AS RECORDED IN 1968 AS PER LAND CORNER RECORD, ACCEPTED CORNER POSITION AS IT MATCHED THE BEARING TREES FOUND.

EXISTING CEDAR 12" S 69°E 71.65'	EXISTING CEDAR 17" N 46°W 61.86'	EXISTING CEDAR 17" N 19°W 68.78'
--	--	--

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

THE CORNER IS A 3" BRONZE TABLET ON A 2" GALV. PIPE APPROX. 1.5 ABOVE THE GROUND STAMPED AND IN THE ORIGINAL POSITION PER THE 1968 LAND CORNER RECORDATION CERTIFICATE. WE MADE THE FOLLOWING ADDITIONAL REFERENCES. (ALL MEASUREMENTS TAKEN TO NAIL IN SIDE OF TREE)

BALSAM 7" S 46°W 11.85'	STEEL SIGN POST NE 0.50'
----------------------------------	-----------------------------------



Signed by

*Steven R. Applekamp*

NOVEMBER 9, 2000

Surveyor's Michigan License No.

43045

LIBER

8 PAGE 189