	SON COUNTY	\circ		0	į		0
	D LAND CORNER 343 of 1990	O.A.A.B.C.	CTION 20, WATERLO		SUR IEMONU	IVEY & MENTATI	ION
Pate For corners i	• •	Filing Require	ment of Act 74, Mich.		MAR 1	3 2000	
	County)	Located In:	Corner Code ≠		SEC	TION	
1. Public Le	ind Survey	T R T R T R	D-8			2126313 Page: 1 of	' 1 10.560
Property in Section Miscellar Property	n S_ seous S_	TR TR TR	Hindy Reilly -		contain of Deeds Sta	L-1609 P-	-412 Imber
	, Record	T R ed Plat		^^	8 C D E	FGHI	J K & M
ALAN L.	SCHEPPELMAN in a	field survey on	NE 11 90	8 5	7 8	3 - 10 -	-1112
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:					19 29	21 22 28 27	23 24 25
	more than 4 corners his certificate.	, all in the same town and	range, may be recorde	d 11 12 13	31 32	33-1-34-1-	35 36
Description of original monument and accessories and/or subsequent restoration:							
POINT	NOT SET IN ORI	GINAL GOVERNMENT SU	JRVEYS.				

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

THE CENTER OF SECTION WAS ESTABLISHED BY INTERSECTING THE EAST-WEST 1/4 Line with a line projected through a 2' diameter concrete post from the north 1/4 post. The position of the center of section agrees within 0.5' for measurements to property corners and the East 1/4 post. Set a 4" \times 30" cast iron Harrison Marker Stamped "D-8 tis r2e is 35998" in the north shoulder of the road at the top of Bank, 0.4' below the surface.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

CHE OF MICHALL ALAN SCHEPPELM.
PROFESSIONAL SURVEYOR
No.
35998 4" x 30" CAST IRON HARRISON MARKER WITH BRASS CAP STAMPED "D-8 T1S R2E LS 35998" - 0.4' BELOW GROUND IN NORTH SHOULDER OF ROAD. NORTH CENTERLINE OF 1" STEEL BAR IN TOP OF 2' DIAM. CONC POST 10.97 N70°E SET NAIL & TAG 35998 SE SIDE OF POWER POLE 100.66 S01°E SET NAIL & TAG 35998 EAST SIDE OF 15" HICKORY 87.521 CENTERLINE OF EAST-WEST ROAD SOUTH 15.15' N11°W SET NAIL & TAG 35998 EAST SIDE OF 8" RED OAK 94.56 SOUTH SURVEY MARKER SIGN POST 40.60 07/08/98 35998 Surveyor's Michigan License No. FOAR APPROVED BY INICHICAN STATE BÖARG OF LAND SURVEYORS, JAN. 20, 1971 Revised May 14, 1975 Revised Jan., 1963