

For corners in

Corner Code #

(County)

2000 REMONUMENTATION

1. Public Land Survey

T 25N R 5W

G-9

T R

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous Property in Se

S T R

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims

A	B	C	D	E	F	G	H	I	J	K	L
1	6	5	4	3	2	1					
2											
3											
4	7	8	9	10	11	12					
5											
6	18	17	16	15	14	13					
7											
8	19	20	21	22	23	24					
9											
10	30	29	28	27	26	25					
11											
12	31	32	33	34	35	36					

A. Description of original monument and accessories and/or subsequent restoration:

G-9: Sec. Cor. Common to Secs. 21, 22, 27 & 28, T25N-R5W, Garfield Township

July 29, 1852 GLO Resurvey by George H. Cannon, set post for corner; Yellow pine 14" N 37° W 32 links; Yellow Pine 10" S 11° E 20 links.

May 7, 1981 LCRC Farrier Surveying Liber 2 Page 307, set 1/2" rod and cap #24594 15' W of N-S trails, held centerline of Fletcher Road for N-S and single proportioned for E-W: S 48° W, 45.17', wood post; N 08° W, 91.00', 8" R. Pine; N 47° E 97.45', B. Cherry; S 64° E, 100.52', 10 R. Pine.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-9: Sec. Cor. Common to Secs. 21, 22, 27 & 28, T25N-R5W, Garfield Township

Found Iron and Cap #24594 recorded in Liber 2 Page 307; 1.3' S of E-W Road and 15' W of N-S road N 08° W, 91.00' found nail in 12" R. Pine.
No G.I.O. witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9: Sec. Cor. Common to Secs. 21, 22, 27 & 28, T25N-R5W, Garfield Township

Found Iron and Cap #24594 recorded in Liber 2 Page 307; 1.3' S of E-W Road and 15' W of N-S road. Added 5/8" iron with brass cap in mon box.

S 73° W, 83.76' PK in wood post marking tel. riser found

N 08° W, 91.00' nail in 12" R. Pine found

S 33° E, 112.10' nail in 12" Oak found

S 25° E, 65.8' stop sign

Kankaska County Peer Group accepted the above monument as a careful and faithful reestablishment of the position of the original corner.

**Ratified by Peer Group
P.A. 345 - 1990 Kankaska County**

Chairman Lynne Turner

Date 2-94-01

Signed by [Signature]
Surveyor's Michigan License No. 24594

Date 2-14-01



3026810

Page: 1 of 1

02/16/2001 10:26 AM

REMON
LB: 6 PG: 139

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
REVISED OCT., 1995