OCT 0 6 1997

Surveyor's Michigan License No.

COMMISSION   LAND CORNER RECORDATION CERTIFICATE	22 RECEIVED FOR RECORD 28 SEP 26 AM 11 10 CLERK - REGISTER RECORD Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H   J K   2
<ul> <li>Management or by a decree of a Court of Law and/or that the corner points mentioned in this c, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:</li> <li>NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.</li> <li>Description of original monument and accessories and/or subsequent restoration:</li> <li>1829 - E. H. Lytle, D.S., Set quarter Sec. post in prairie and raised mound.</li> </ul>	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 13
1873 - Ed Strong, C.S., "U.S. Standing" 1879 - F. Hodgman, C.S., "At proportional distances between Section corners 1 & 4 (in Sestone with brick around".  B. Description of comer evidence found and/or method applied in restoring or reestablishing of Found nail & tab in pavement. Dug and found iron in mon. box with no lid. Removed ir basketball size stone directly under about 1.5' below grade. Stone was surrounded by re	corner: on & box and found a
iron in box and stone were all at same position.  BY KAL REM P	RATIFIED AMAZOO COUNTY ONUMENTATION EER GROUP 9-18-1997
Found stone is accepted as a careful and faithful perpetuation of the position of the original corner. Placed Harrison Monument over stone with monument box over, Accessories:  Railroad rail fence post East 28.8' Nail & Tab in S.W. side of 20" Cottonwood S. 30° E. 47.9' Nail & Tab in South side P. Pole N. 80° W. 52.4'	ALLEN H. McMACHEN PROFESSIONAL SURVEYOR No. 16935

REVISED MAY 14, 1975 REVISED JAN., 1983