

JAN 15 2000

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Lenawee
(County)

Located In:

Corner Code #

LIBER 1 PAGE 338

STATE OF MICHIGAN
LENAWEE COUNTY
FILED

1 SEP 1999 5:44:46 PM

VICTORIA J. DANIELS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey T-9-S R-2-E C-3
T R
T R
T R
2. Property Controlling S T R
In Section S T R
3. Miscellaneous S T R
Property in Sec S T R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on July 12, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1824 John Mullett set post cor. Sec.'s 5, 6, 7 & 8 Butternut 6 N 10 E 8 Buckeye 6 S 74 W 15
1880's James Blair described the corner as stake & bricks. Buckeye 6 N 16 E 6 1/2
1900-1903 Survey of Ohio-Michigan boundary called for iron hub in tile. Blaze on buckeye tree N.E. 3.8
1935 The corner is part of the boundary of Assessor's Plat No. 1 City of Morenci
1936 The corner is part of the boundary of Assessor's Plat No. 2 City of Morenci
1998 The corner is in a cultivated field. I found the bottom 6" of concrete monument. I set a Harrison Monument by retracing both of the Assessor's Plats using the plat monuments from the north

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 12, 1999 Found Harrison Monument

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Harrison monument stamped P.S. 13040 buried 12" deep in cultivated field and is accepted as the best available evidence of the position of the original corner

State line Post #29 S 55° E 474.99
Carsonite Post East 160'
Survey mark spk & re-mon tag in S. face 24" Walnut N 70° E 155.01
dbl hd nail & re-mon tag in E. face 66" Cottonwood N 10° W 193.43
dbl hd nail & re-mon tag in S. face 9" Cottonwood S 70° W 88.01



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date July 20, 1999

Signed by Glenn E. Richard Date Aug. 23, 1999
Glenn E. Richard

Surveyor's Michigan License No. 13040