•	LAND CORN	ER RECORDATION CERTIFIC	CATE	_ 🖵	. ##
For communication	Filing Requir	rement of Act 74, Mich. P.A.	1970	Dec 2	TO THE PARTY OF TH
For corners in Livingston	Located In:	Corner Code ##		ANC SIST GST	ित्त् चर्म
(County)	Located in.	Comer Code		A SECOND	FILED
Public Land Survey	T <u>lN</u> R <u>4E</u>	A-1		AVILV COUL	
	T R T R				
	T R				· .
2. Property Controlling					
in Section 3. Miscellaneous	S T R S T R		.S.C.#117m Register of Deeds	s Stamp & File	Number
Property in Sec.	S R		megiater of Deed	, Junip & The	
4 Lot No Re	corded Plat				
				, , , , , , , , , , , , , , , , , , , ,	
			3 5	4-3-	2
			4 - 7 - 8	910-	1-11-12-
Darrell D. Hughe	Sin a field survey onDe	ecember 17, 1999 93 Lof 1970, the corner points mentione	5		
in lines 1 and 2 above were in	conformance with regulations a	nd rules therefore as required in th	ie ji ji	/ 16 - 15-	14-13-
current manual of survey instruct Management or by a decree of a	ations of the United States Depa Court of Law and/or that the corn	rtment of the Interior, Bureau of Lan er points mentioned in lines 3, 4 and	iù [] [21-22-	23 24
above were in conformance with	the rules of the Michigan Board	of Land Surveyors or by a Decree of monumented, recovered, found a	a		
expressed below:			10 30 25	28 27-	26-25-
NOTE: Not more than 4 co- on this certificate.	rners, all in the same town a	and range, may be recorded	11 12 31 3		
,			13	33 34	
 A. Description of original m 	onument and accessories ar	nd/or subsequent restoration:			
GLO: 1825		,			
	ak 19" S40W 9 lks ak 15" S40E ll lk				
B. Description of corner evi	idence found and/or method	formation on back of applied in restoring or reestable p) 0.2' below grave	ishing corner:		
		•	Gur.	Vijiz o	
			FEMORIO		
	·			1993	
	1		COM	MOSCON	
A-1. T1N, R pipe, affixe Monumentation faithful rees 258 DEG. 20.7 065 DEG. 30.5 167 DEG. 80.8	4E, PUTNAM, replad with 2" dia Corner, P.S. tablishment of the	19834, and is acc ne position of the N/S WOOD COR. FENCE S/S UTILITY POLE. N/S 32" CHERRY.	r with 1-1/4 stamped "L epted as a original cor	" X 36" ivingstor careful	
	•			, ut	HICHIO
\wedge	10.			DAR	RELL
sing by / and		Approved by Liv. Co	o. Peer Group cember 27, 1993	: Nov. 1から	1993

Surveyor's Michigan License No. ___

19834

IOSCO TOWNSHIP, T2N, R3E

M-13, SOUTHEAST CORNER SECTION 36

FIELD 10-26-93 D.D. HUGHES AND ASSOCIATES, FOWLERVILLE

Found 1/2" iron rod (no ident. cap) 0.2' below gravel road, at centerline gravel to south (Dutcher Road), 8' north of centerline Schafer Rd. to East., fence to west.

1825, corner first set by Sylvester Sibley, Deputy Surveyor.

1895, Miles Bullock shows tie and distances to all 1/4 corners.

1915, Grant Dunning shows corner in Sec. 36 survey and common to all townships.

1964, Munsell and Garlock research notes for Iosco/Unadilla line with fallings.

1970, Garlock shows ties to NW cor. Sec. 6, T1N, R4E

1971, Kostecke surveys West 80 acres of NW1/4 Sec. 6, Putnam. Fd.1/2 rerod.

1972, Henderson, Bates, Elrich and Schuler, Lapeer Mi., show 1/2" rod in survey of part of Sec. 6, Putnam, for Detroit Edison.

1976, Act 74, filed by Oscar Boss, for survey in Sec. 36, Iosco.

1977, Act 74, filed by John Albright, for survey in Sec. 6, Putnam for Detroit Edison.

1978, Patrick Benton shows corner in survey of Sec. 31, Marion Twp. (no witness' or corner type).

1979, Charles Garlock shows 1/2" iron rod in Sec. 36, Iosco Twp. survey.

1979, Larry Bryan shows corner Sec. 36, Iosco Twp. survey.

1984, revision to Detroit Edison survey showing corner common to four townships.

1988, Gary Boss shows corner in SE1/4 Sec. 36, Iosco Twp. survey.

1989, Greg Stephens, Detriot Edison surveyor, files Act 74, calling for 1/2" bar.

I can follow witness ties back to Garlock 1970, one original tie remains in stump. I conclude this 1/2" iron rod to be the corner common to four townships and used by the surveyors listed above.