UMENTATION)		Ç,
CEC 1 3 1993	·			
	AND CORNER RECORDATION			
Fi	ling Requirement of Act 74, I		Nov.	:•}
Corners in I Contend to Contend t	lier Oarran Oada a		NC N	
County)	Ein: Corner Code =	<i>14</i>	awoy asto	
Public Land Survey T_4	<u>R_6</u> . <u>L-13</u>		BA43	FILED
	R			5
τ	R			
	R		1 03	
Miscellaneous S T	R		eds Stamp & File Numb	ber
Property in Sec. S <u></u> T	R			
Lot No , Recorded Plat		A B C	DEFGHIJ	KLM
Private Claims		2		
		3		
Edward Anderson , in a field survey (on August 20.	19 <u>93</u> 5	-8-9-10-11-	
ereby certify that under requirements of P.A. 74 es 1 and 2 above were in conformance with	, Michigan P.A. of 1970, the corner poi	intsmentioned 6	-17-16-15-14-	13
ent manual of survey instructions of the United	States Department of the Interior, B	Sureau of Land 7		
agement or by a decree of a Court of Law and/or e were in conformance with the rules of the Mic	chigan Board of Land Surveyors or by	yaDecree of a	-20-21-22-23-	24
t of Law; established, re-established, mon essed below:	umented, re-monumented, recover	red, found as 10	-29	25
E: Not more than 4 corners, all in the s	ame town and range, may be re			
on this certificate.		1231 13	-3'23'33'43'5	36
Description of original monument and acc	cessories and/or subsequent res	storation:		•
GLO NOTES DATED APRIL 5, 182				
GLO WITNESSES W. Oak 15"	S40°E, 28 LKS			
W. Uak 12"	N11°W, 29 LKS			
ADDITIONAL VICTORICAL DATA ON				
ADDITIONAL HISTORICAL DATA ON	BACK OF SHEET			
Description of corner evidence found and	/or method applied in restoring	or reestablishing corner:		
Found 1/2" x 18" Iron fit Wit	nesses by Connenstand F	Engineering Boss Eng	zinooning	
Garlock (Profeessional Survey			jineering,	
	1			
	1			
	· .	· .		
l.				
1 • •				
Description of monument for corner and a	ccessories established to perpe	stuate locating the position o	if the comer:	
L-13 SOUTH 1/4 Corner Sec	36, T4N-R6E			
SET 1 1/4" x 36" Brea in centerline of Holt	kaway Iron Pipe with Br forth Boad	ass Cap (Livingston	Co. Mon. Cor.)	
N65°W 63.94' Spike E				
N15°W 42.52' Spike E/	S 18" Wild Cherry			
N45°E 42.74' Spike E/ West 72.35' to 1/2" i	S 14" Oak ron in Roadbed			
			LIVINGSTON COUNT ON PEER GROUP	Y
	E OF MICH	OCTOBER 20,		
Sall.	1. * EDWARDE	Date November 2, 199	33	
ed by Carlend	JUI SURVEYOR &	Date Novellber 2, 195	<u>· · · · · · · · · · · · · · · · · · · </u>	
eyor's Michigan License No. <u>11495</u>	NO. NO.	FORM APPROVED BY MICHIGAN		RAY 14, 1975
· · ·	NO. 11495 Surveyors		REVISED	D JAN., 1983
4	AL CONCORT	. M. S		
•			• • • • • • • • • • • • • • • • • • • •	•



approv

401 S. Leroy St. Fenton, Michigan 48430-2164

EDWARD E. ANDEHSON, P.S., P.L. RICHARD F. FRANK, P.S. BR. HALTZ, C.S.

Michigan Society of Professional Surveyors American Congress on Surveying and Mapping American Society of Civil Engineers

> (313) 629-8974 FAX (313) 629-9069

September 24, 1993

SUMMARY

L-13 SOUTH 1/4 CORNER, SECTION 36, T4N-R6E, TYRONE TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN

Found 1/2" iron in centerline gravel road (Holtforth Road).

Cornerstone witnesses, Pages 9B and 15, this dossier. Found all witnesses, and they field checked to the iron we found.

Anderson, Boss, and Garlock witnesses, Pages 6B, 7, 8B, 11B, 12 and 14, this dossier. Found one witness to the north; witnesses to the south were gone. Witness to the north field checked to the iron we found. Measured from iron we found at S 1/4 Corner to the SE corner of Parcel 6 (that we found); Boss survey Page 6A this dossier. Measured distance checked within 0.14 of distance shown on said Boss survey.

Distances from S 1/4 corner to S.W. corner of said Section 36 was 2653.87 per Cornerstone, Page 9A this dossier and 2655.43 per Anderson, Page 11A this dossier and 40.32 chains equals 2661.12 per Garlock, Page 13, this dossier.

Distances from S 1/4 corner to the S.E. corner of said Section 36 was 2679.52 per Boss, Pages 6A and 7, this dossier and 40.25 chains = 2656.50' per Garlock Page 13 this dossier.

Also, found the N 1/4 of Section 1, T3N-R6E, Hartland Township, Livingston County, Michigan (1/2" iron) by rough measurement to the west (using 1/2the distance of the jog at the S.W. of said 36) and found a 1/2" iron at the N 1/4 corner of said Section 1, and the distances between the S 1/4 of said 36 and the N 1/4 corner of said Section 1 measured 72.35'.

Gravel road (Holtforth Road) running East and West. No occupation to the south. Found an old fence line running to the north.

Made a clean sweep of the immediate area and found no other irons or corners.

Terrain is fairly flat North, South, East, and West. Corn field to the south and heavy woods to the north.

Came to the conclusion that the 1/2" iron we found was the correct S 1/4 corner of said Section 36.

11.11 Anderson Edward E. ANDERCON P.S. #11495 -SURVEYOR & ENGINEER RO 11495 Unrayor s.?