

**MAR 13 1998**

**MACKINAC COUNTY REMONUMENTATION CORNER**

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**

**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Mackinac  
(County)

Located In:

Corner Code ##

1. Public Land Survey T 40N R 3W
- T        R
- T        R
- T        R
2. Property Controlling S        T        R
- in Section S        T        R
3. Miscellaneous S        T        R
- Property in Sec. S        T        R

PCC NE Cor  
PC19

#3

**RECEIVED & FILED**  
**DIANE FRANKOVICH**  
MACKINAC COUNTY REGISTER OF DEEDS

**DEC 29 1997**  
AM 7 | 8 | 9 | 10 | 11 | 12 | 1 | 2 | 3 | 4 | 5 | 6 PM

**Register of Deeds Stamp & File Number**

4. Lot No.       , Recorded Plat
5. Private Claims

I, Neil E. Hill, in a field survey on DECEMBER 22, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

- A. Description of original monument and accessories and/or subsequent restoration:
- |      |           |             |           |             |
|------|-----------|-------------|-----------|-------------|
| 1840 | GLO notes | Austin Burt | 5" Spruce | N70W 12 lks |
|      |           |             | 4" Spruce | S33W 23 lks |

No records of this corner being perpetuated  
Corner & line shown on Arnold's Replat  
T.L. Jackson may have set and used this corner

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997 Found no evidence of corner. Used found "T"-iron set by C.A.&E and used Section corner to push line Easterly to set Northeast corner of P.C. 19.

ACCEPTED BY THE MACKINAC COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER P.A.  
345 OF 1990 AT A MEETING  
HELD ON 12-12-97

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set rod and cap under eave of Mackinac Abstract 1.5 feet off building face.

SW cor	N70W	08.65'
SE cor	S80E	27.83'
East gate cor	S30W	36.18'
West gate cor	S45W	44.10'



Signed by Neil E. Hill P.S. Date DECEMBER 22, 1997

Surveyor's Michigan License No. 27447