MAR 1 3 1998

MACKINAC COUNTY REMONUMENTATION CORNER

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE

Filing	Requirement	of	Act	74,	Mich.	P.A.	1970

Mackinac_ Located In: Corner Code -44 T 41N R 3W MC A-11/B-11 1. Public Land Survey __ R E-W Sec line Sections 30 & 31 R 2. Property Controlling _ T _____ R _ in Section 3. Miscellaneous Property in Sec.

AECENEO A FILE DIANE FRANKOVICH WIT OFFICIENT OF DEEDS

DEC 29 1997 718 9 20 22 22 21 21 3 6 5 6

Register of Deeds Stamp & File Number

10

11

4.	Lot No, Recorded Plat
5.	Private Claims

Neil E. Hill DECEMBER 22 , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: 6" Tamarack S18W 55 lks

GLO notes William Burt No records of this corner being perpetuated, however various surveys indicate this corner's position GLO notes 211.2' East of Section Corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997 Found no evidence of corner. Set on extension of E-W Section Line East. Found "T"-iron 220.30' West of Section Corner at Mackinac Trail R.O.W.

> ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING 15-15-97 HELD ON

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

85

Set 1/2" rerod with remonumentation cap at 211.20' East of Section Corner at edge of tree line, 235' from water of Lake Huror

14" W. Pine N80W 70.00

12" W. Pine N15W 13.05

5" Cedar N35E 09.26'

6" Cedar S20W 12.35'

neil E HILL Land Surveyor No. 27447 ukaj G

DECEMBER 22, 1997

bell Signed by _

_ Date _