1994 Mackinac County Remonumentation Corner.

SURVEY & LAND CORNER RECORDATION CERTIFICATE For Reference in Macking PR 1 0 1995 Located In: Corner Code ##	REGRIVED & FILLD
Macking R 1 0 1995 Located In: Corner Code ##	DIAME FRANCOSCIONAL MACRIMAC COLUMN STORES OF THE STORES O
1. Public Land Grand T 42N R 4W C-13	MOV 0 9 1994
T R	AM FAN 7[8]9]10[23]27[4]3[8]4[5]6
7 R	A
in Section S T R	ster of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L M
J. Private Claims	2 6 5 4 3 2 1 1
I, David B. Guthrie in a field survey on April 20 , 19 94 ,	4 7 8 9 10 11 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the	6 18 17 16 15 14 13
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5	7 8 10 20 21 22 23 24
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as	9
expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded	10 30 29 28 27 26 25
on this certificate.	12 31 32 33 34 35 36
Ironwood 6/NW/9 1977: Survey by Larry Feindt. Found large steel spike. 1980: Survey by Orlando Doyle. Found railroad spike. 1988: Survey by James Granger. Found railroad spike. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1994: Found railroad spike in Monument Box.	
ACCEPTED BY THE SURVEY PEER GRO OFFICIAL CORNER 345 OF 1990 AT A M HELDON 6-16	UNDER P.A. EETING
11-09-94	hange
C. Description of monument for corner and accessories established to perpetuate locating the 1994: Set Mackinac County Remonuemntation Corner. \$\frac{1}{4}5/8\frac{1}{8}\$ by 24\frac{1}{8}\$ Iron Rod with a 3\frac{1}{8}\$ aluminum cap stamped corner set within a monument box.	
Referenced: N17°W - 37.00 feet - Steel Post (Exist.) S16°W - 34.90 feet - Cor. Fence Post (Exist.) S45°E - 48.10 feet - Fence Post (Exist.) N62°W - 83.28 feet - Utility Pole	DAVID B. GUTHRIE LAND SUI:VEYOR NO. 22435
Sigged by Pal B. Tuhu Date Oct, 2	1,1994
22435	ED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983