

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N.R. 7 W.


Mackinac COUNTY

DESCRIPTION OF CORNER South 1/4 Corner of Section 33 on South boundary of Township

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/24/63

WITNESSES TO CORNER..... 12" Cedar (1/4 S. 33 N.B.T.) N. 85° W., 32 Lks.



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at 3/4" Iron Pipe. Found Tamarack stump bottom bearing N. 80° W. 33 Lks. for an original bearing tree. Corner lies in Intersection of the old Trout Lake Road to North and East.

Note: North 1/4 Corner of Section 4, T. 43 N., R. 7 W. lies 31 Links West of this Corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 1/27/64
REGISTERED LAND SURVEYOR