

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2016 State Survey and Remonumentation Grant Agreement

- Notes:**
- No more than two Original Public Land Survey Corners can be recorded on this certificate
 - If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
 - If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County Edenville Twp.

Corner Type	Survey Township				Corner Code
Original Public Land Survey Corner	T	16N	R	1W	D7
• MCL 54.202(g)	T		R		
• MCL 54.262(g)	T		R		
	T		R		
Property Controlling Corner	S	T	R		
• MCL 54.202(i)	S	T	R		
• MCL 54.262(h)	S	T	R		
	S	T	R		
Protracted Public Land Survey Corner	T		R		
• MCL 54.202(k)	T		R		
• MCL 54.262(i)	T		R		
	T		R		

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6			5		4		3		2		1		2
3														3
4	7			8		9		10		11		12		4
5														5
6	18			17		16		15		14		13		6
7														7
8	19			20		21		22		23		24		8
9														9
10	30			29		28		27		26		25		10
11														11
12	31			32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

- D7 -- 1832 -- GLO -- H. Parke -- Set qr. Post
- 1) Hemlock 10" N63°W 13 L.
 - 2) Maple 15" N85°E 17½ L.
- 1852 -- GLO Dependent Resurvey -- A. Burt -- Old qr. Corner. Set Post
- 3) Hemlock 8" S60°W 21 L.
 - 4) Hemlock 9" N30°E 20 L.

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

D7 – ¼ Corner common to Sections 17 & 20, T16N, R1W – No conclusive GLO evidence found. Set DNR Monument by single proportion between 'C7' and 'E7' holding record GLO angle per 1852 Resurvey. Measured Grid Bearing and distance as follows: N89°23'45"W 2614.66' (N89°44'W 2630.76' – GLO) to 'C7' and S89°44'45"E 2631.72' (N89°55'E 2647.92' – GLO) to 'E7'. DNR monument accepted as a careful and faithful reestablishment of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

D7 – Stamped 4" Aluminum Cap on 1" x 36" long galvanized iron pipe. Set Blue Composite Post 1' North S49°E 21.04' to set Nail and Tag (N & T) in SW side Twin 7" and 10" Red Maple
S2°E 23.92' to set N & T in W. side twin 15" White Oak scribed 'XBT'
N17°W 33.72' to set N & T in W. side 19" Oak scribed 'XBT'
N44°E 63.81' to set N & T in NW side 22" White Oak scribed 'XBT'

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
07/28/2016	N43°46'13.7226"	W84°27'26.5373"	NAD83(2011)	2010.00

Set by double side shot from 3 GNSS control points that were established from static baselines from 2 local OPUS base stations.

I, Craig W. McVean, in a field survey on July 28, 2016, certify under the requirements of the State Survey and Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the Corner Recordation Act, 1970 PA 74, MCL 54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuated or monumented as described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.

Craig W. McVean 12/7/2016
Craig W. McVean Date

Professional Surveyor's License No.: 39088

Department of Natural Resources, 8015 Mackinaw Trail, Cadillac, MI 49601



I, Brian D. Ferguson, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on 08/03/2016 and is accepted for filing in the Midland County Remonumentation Program.

Brian D. Ferguson Date

Professional Surveyor's License No.: 26454