

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
 Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2016 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County

Edenville Twp.

Corner Type	Survey Township			Corner Code																	
Original Public Land Survey Corner	T	16N	R	1W	C10	1	A	B	C	D	E	F	G	H	I	J	K	L	M	1	
• MCL 54.202(g)	T		R			2		6		5		4		3		2		1		2	
• MCL 54.262(g)	T		R			3															3
	T		R			4		7		8		9		10		11		12			4
	T		R			5															5
Property Controlling Corner	S		T		R		6		18		17		16		15		14		13		6
• MCL 54.202(i)	S		T		R		7														7
• MCL 54.262(h)	S		T		R		8		19		20		21		22		23		24		8
	S		T		R		9														9
Protracted Public Land Survey Corner	T		R			10		30		29		28		27		26		25			10
• MCL 54.202(k)	T		R			11															11
• MCL 54.262(i)	T		R			12		31		32		33		34		35		36			12
	T		R			13															13

Part A: Corner(s) History

C10 – 1832 – GLO – H. Parke – Set ¼ Post

- 1) Pine 11" N52°E 9 L.
- 2) Beech 9" S15°W 20 L.
- 3) W. Pine 10" S51°E 11 L.
- 4) Maple 8" N38°W 11 L.

- **1852 – GLO Resurvey – A. Burt – Old qr. corner – Set Post**

- **1908 – CSR L. 1, p. 252 – F. J. Gibbs – Section 30 Survey – Set piece of 1 ½" gas pipe at average distance on true line. No bearings to be found.**

