

REMON CORNER M-5, WARREN TWP.
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Midland

(County)

Located in:

Corner Code #

1. Public Land Survey

T 16N R 2W

M-5

T R

T R

T R

S T

S T

S T

S T

SURVEY &

REMONUMENTATION

FEB 29 2001

SECTION

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, RODNEY CLAYPOOL, in a field survey on March 2, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-5 Corner common to Sections 12 and 13 on East townline

Survey by Glo, 1830's, set post

Survey by F. Gibbs, 1904, old post standing

Survey by M. Robison, 1992, found painted X

LCRC by P. Lapham, 1979, chiseled "X" in concrete

LCRC by D. Ledy, 1988, set RR spike per P. Lapham witnesses

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-5 Corner common to Sections 12 and 13 on East townline

Found RR spike shank at position per survey by M. Robison and LCRC's by P. Lapham and D. Ledy.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5 Corner common to Sections 12 and 13 on East townline

Replaced RR spike with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 and is accepted as the best available evidence of the position of the accepted corner.

N 45 Deg W, 48.13', chiseled "+" in North end concrete pipe

S 45 Deg W, 64.80', large nail in telephone pole

S 45 Deg E, 76.77', MDOT nail and disc in power pole

S 60 Deg W, 43.15', chiseled "+" in South end concrete pipe

South 22.44', Edenville Twp. corner A-5

East 4.5', centerline M-18

North 5.0', centerline road to West

544


STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES

Register of Deeds Stamp File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													



Signed by Rodney D. Claypool
Surveyor's Michigan License No. 29241

Date 12-26-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971

Revised Jan., 1983

