REMON CORNER M-7, WARREN TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

546 For corners in Midland STATE OF MICHIGAN (County) Located in: Comer Code # KIDLAND COUNTY REMONUMENTATION & FILED 1. Public Land Survey 16N R 2W R 12/28/2000 8:44:27 AM R REMONUMENTATION SCOTT I. HAINES 2. Property Controlling S REGISTER OF DEEDS in Section S T 3. Miscellaneous S Т R FEB 23 2001 Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat SECTION C 1 5. Private Claims DE F G н 3 6 I, <u>RODNEY CLAYPOOL</u>, in a field survey on <u>June 11</u>, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required 2 3 in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules 4 8 9 10 5 18 17 16 15 14 6 of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below: 7 8 19 20 21 22 23 NOTE: Not more than 2 comers, all in the same town and range, may be 9 recorded on this certificate. 30 29 28 27 26 10 11 31 32 33 34 35 12 A. Description of original monument and accessories and/or subsequent restoration: 13 M-7 Corner common to Sections 13 and 24 on East townline Survey by Glo, 1830's, set post M 1 C 4 Survey by F. Gibbs, 1904, stone set in road Survey by MDOT, 1937, used corner Survey by M. Hunter, 1954, found wood stake in monument box RODREY D. Survey by D. Ledy, 1987, found monument box CLAYFOOL LCRC by P. Lapham, 1979, found monument box LARD MOYEVAN

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-7 Corner common to Sections 13 and 24 on East townline

Found rod in monument box at position per survey by MDOT, M. Hunter, D. Ledy and LCRC by P. Lapham.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M-7 Corner common to Sections 13 and 24 on East townline

Replaced rod with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 and is accepted as the best available evidence of the position of the original corner.

S 60 Deg W, 44.25', chiseled "+" on top East end headwall N 70 Deg W, 54.84', chiseled "+" on top West end headwall N 55 Deg E, 61.69', spike in power pole S 45 Deg E, 74.09', railroad spike in power pole (BM #410) North 5.60', Edenville Twp. corner A-7


Signed by Surveyor's Michigan License No.

12.26-00 Date

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971

Revised Jan., 1983

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY



25241

4489

2 1