

L

McQUEEN 1781 Harwood
15700 15 TOWN CORNER

S.W. Cor. Sec 18

44.6' S-VI 12" Poplar

30.0' N 12" Maple

1630.5' to Section Corner East

County Hwy. Mc Gray - Chained to known
Corners N-S-W-E - reset this point. No
mark left in road


RESET FROM TREE WITNESSES - DROVE 6" SPIKE
ON FENCE LINES - E-SIDE 2000 ROAD N.
IN & N. 6480

S.E. Corner Section 18.

S 25° E 39.25 12" pine

S 26° E 54.91 10" pine

Also



RESET FROM TREE WITNESSES & DROVE 6" SPIKE
COMPARED TWO HUBS
INCL. OF C. 450 AND ON FENCE LINES
NORTH AND SOUTH.

NOTES FROM CHDC

Section 18, 18.

18. Section 18, 18.

Then left on S. 25° E. road and
road both ways. No corner there.
Set rock over point.

With witness, found the corner.
We found the bolt and drove a 6" x 3/4" pipe
replacing the bolt in the top. Top of hole 50'.
Set monument 33' N. along a line - 33' 30" -

From Center Section

Power Pole N 43° W

Telephone pole S 43° 30' W

West 1/4 Section 18.

Fence line and wood in the Road Barri
Ways. Said by Pan Johnson & Mc King - to be
corner, Set by Harvey.

White Sign post S 62° E 16.7
Power Pole N 67° E 42.0
" " S 15° W 93.5

White Sign post N 17° W 63.6

V.L.S. Eying 50' steel pipe, found a corner. No mark
found. Adjacent corner.