

SURVEY &  
REMONUMENTATION

MARQUETTE COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

JOB NUMBER: 94030  
SHEET NO. : 1-483

APR 28 1995

LAND CORNER RECORDATION CERTIFICATE

1994 DEC 28 PM 5:56

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 47N R 24W  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

M-10

2. Property Controlling  
in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous  
Property in Sec.

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

*Patricia A. Monley*  
REGISTER OF DEEDS

LIBER 1 PAGE 154  
Register of Deeds Stamp & File Number

I, GERALD W. CARLSON, in a field survey on Tuesday, December 13, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

M-10: East 1/4 Corner of Section 25. 1844: William A. Burt's monument at point of old stake. Referenced by:  
original survey notes describe the corner monument as a wood 5" Tamarack N31E, 18.2' 6" Tamarack S31E, 4.3'  
post referenced by: 6" Tamarack S83W, 8.25' 6" Tamarack N01W, 16.6'  
9" Tamarack N28E, 14 L 12" Tamarack N47W, 65 L L. 5 R.C., Pg. 358.  
1992: Land Corner Recordation Certificate recorded by Paul Bressette LLS No. 37270 indicates a found 1" iron pipe, Tamarack stub NE with axe marks and Tamarack stump NW in proper position for OETs. Excavation at pipe revealed 3 stake points, one considerably older than others. Set DNR

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted DNR monument as referenced by Paul Bressette, P.S. No. 37270 in Part A above.  
Distance North is 2643.30' and distance South is 2650.75'.

RATIFIED BY PEER GROUP  
P.A. 345 OF 1990

*Larry J. Bressette*  
DATE 10-27-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Found Department of Natural Resources iron pipe with 4" diameter aluminum cap in place referenced by nails in:  
5" Tamarack N15W 16.96 ft. Bressette NBT  
5" Tamarack N23E 18.28 ft. Bressette NBT  
5" Tamarack S57E 21.47 ft.  
4" Tamarack S50W 24.73 ft.  
Steel sign post South 1.0 ft.  
Monument is 1.0' East of a 3" diameter wood post. Stamped MCR 1994 on cap of monument (Marquette County Remonumentation).  
Bk. 5, Pg. 113

Signed by Gerald W. Carlson  
Surveyor's Michigan License No. 24589

Date 12-22-94

