

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 29W	G7
	T R	(GCDB 400400)
	T 48N R 29W	I7
	T R	(GCDB 500400)
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on G7 09/08/14  
I7 09/15/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G7) Corner common to Sections 15-16-21-22. 1848 - Established by Wells Burt, Deputy. Set spruce  
post. Cedar 14" N21°W 31 links, Cedar 10" S49°E 24 links. Found no subsequent record.

(I7) Corner common to Sections 14-15-22-23. 1848 - Established by Wells Burt, Deputy. Set spruce  
post. Tamarack 12" S11°E 31 links, Spruce 6" N42°W 36 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G7) Remonumented the corner at record bearing and distance from probable US BT Cedar S49°E 24  
links, now a 26" hollow Cedar with old scar inside but no scribing visible. Also at record bearing  
and distance was found Cedar root, no stump left, possible remains of the US BT Cedar N21W 31 links,  
no markings visible. At the position for the corner, found rotted wood, set vertically, now a  
stringy mass in late stage of decay, possibly the remains of the original post. From the position  
monumented, distances to topographic features noted in the 1848 US notes check with the record: Top  
rock knob 15.0 ch. E; Enter swamp 17.5 ch. E; Leave swamp 31.0 ch. E; Stream 20.40 ch. S; Enter  
swamp 1.0 ch. W; Stream 61 ch. W. Distance to G9=5273.24' (5280' US); I7=5269.67' (5277.4' US).

(I7) The original post and accessories were not recovered. After extensive analysis of the  
location of existing corners in this part of the township and of the location of US line calls made  
in 1848, I concluded that reliance upon the topographic features noted in the 1848 US field notes  
results in the most reasonable position at which to reestablish the corner. Consequently, the  
position was reestablished at record distance from: Stream 10 1.70 ch. E; Stream 10 17.12 ch. S;  
Leave swamp 2.0 ch. W; Leave swamp 1.75 ch. N; Top of ledge 100' 77.85 ch. S. The position falls on  
a straight line between monumented corners I9 and I3. Distance to I9=5269.10' (5280' US);  
G7=5269.67' (5277.4' US); M7=10523.87' (10575.8' US); I3=10496.33' (10560.0' US).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
26" Cedar S49°E 16.45' mrkd "S22 NBT"  
12" B.Spruce S24°E 17.55' do  
5" Balsam S62°W 5.9' "S21 NBT"  
11" B.Spruce N01°W 14.95' "S16 NBT"  
Set sq'd cedar post adjacent.  
E= 7928793.405 N= 196806.637

(I7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
4" W.Pine N01°W 26.4' mrkd "S15 NBT"  
6" B.Spruce S75°E 5.05' "S23 NBT"  
4" Tamarack S11°W 14.85' "S22 NBT"  
3" Tamarack S57°W 11.1' "S22 NBT"  
Set sq'd cedar post adjacent.  
E= 7930399.033 N= 196775.403

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/24/2014

For the Michigan Department of Natural Resources, Forest Resources Division

