JUL 0 3 2000

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

1996 NOV 22 AM 11: 07

SECTION

recovered, found as expressed below:

on this certificate.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Patricia	A. Monleys OF DETOS Ogo
REGISTER	OF DEFENS

For corners in Marquette	Located in: Corner Code #				Vate RFC	atticia d. Marleys REGISTER OF DETOS O				
(County)										•
1. Public Land Survey	T 51N R TR TR	28W F13								
2. Property Controlling in Section	S TR S TR									
3. Miscellaneous Property in Sec.	S TR S TR			Registe	LIBER of De	_	-		32 e Num	
4. Lot No, Reco	rded Plat			ъ а		_		_		_
5. Private Claims		·	1^A	B C	Ţ Ţ	F	G H	1		Ť
		Sep 27 1995	3	Î	- 5	_4_				_ -
1. Stephan J. Szyszkoski	, in a field survey on	, 19 do hereby	state that under 4		- e	9	10		11-	 -12-
conformance with regulations and United States Department of the that the corner points mentioned	d rules therefore as require Interior, Bureau of Land N I in lines 3, 4 and 5 above	er points mentioned in lines 1 and a ed in the current manual of survey in- Management or by a decree of a Coun- were in conformance with the rules of Law; established, re-established	structions of the structions of the factor of the Michigan structure of the Michigan structure of the Michigan structure of the Michigan structure of the factor of the fa	-18-	-17	_ _16	15		14-	13-

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

(F13) Quarter corner on the South Side of Section 33. Original corner established in 1845 by Austin Burt: "40.00 Set qr. section post. Sugar 16 N35E 07, Sugar 8 N71W 33".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F13) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner on the Fifth Correction Line at the proportionate North Latitude between monumented corners at E13 and H13, 2623.82' East of E13 and 5247.65' West of H13, being proportionate to the original record. At the position for the corner, I placed a 1"I0x36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, apropriately stamped. From the corner monumented, the Northwest corner of T50N-R28W is westerly, 63.36°.

> RATIFIED BY PEER GROUP P.A. 345 OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F13) Set 1" pipe with 4" MDNR cap.

NDNR monuments are 1" IDV32" iron pipe capped with a 4" dia cost Blazed and scribed the following new bearing trees:

16" Sugar N37W 7.1' "1/4S NBT" 7" Hemlock N45E 10.9' "1/4S NBT" 6" Ironwood \$40E 30.5' "1/48 NBT"

"1/4S NBT" 5" Sugar \$06\ 23.5' Bearings are magnetic.

MDNR monuments are 1"IDx32" iron pipe capped with a 4" dia. cast aluminum Michigan Department of Natural Resources tablet, stamped with Township, Range, corner ID, date of placement, and "PS 33986"

New bearing trees are marked with a BH blaze and a lower blaze at the root crown. The blazes are scribed as indicated in quotation marks at left, with NBT or BT (as noted) being on the lower blaze. Distances are horizontal (unless noted) and measured from the corner to the inside of a notch cut into the bottom of the lower blaze.

STEPHAN J SZYSZKOSKI LAND SURVEYOR

Signed by

11-5-96 Date

For the Michigan Department of Natural Resources - Forest Management Division