

**SURVEY &
REMONUMENTATION**

LIBER 291 PAGE 413

964

APR 24 1995

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in **COMMISSION**

Missaukee
(County)

Located In:

Corner Code M-4

- | | | |
|------------------------------------|----------------------------|------------|
| 1. Public Land Survey | T <u>21</u> N R <u>8</u> W | <u>M-4</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

MISSAUKEE COUNTY MICHIGAN

RECORDED **NOV 23 1995 11:47 A.M.**

Paula F. Lane
Register

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, J. Dean Geers, in a field survey on November, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

- M-4) 1837 GLO Quarter Section post by John Brink, Deputy Surveyor
Aspen 10 S 41° W 15, Aspen 12 N 16° W 25
- M-4) 1928 MDOT Plans, Project #057-16, File #J-17-A-6: No corner indicated
- M-4) 1981 McClung LCRC, Liber 1, page 678: Computed position only, no corner set
- M-4) 1981 McClung survey, Liber S-2, page 133: Computed position
- M-4) 1982 McClung survey, Liber S-2, page 136: Computed position

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- M-4) Quarter Section corner common to Section 12, T21N, R8W and Section 7, T21N, R7W

No corner was found. Corner was reestablished at the computed position as recorded being on line with the Section corner to the North and South and in fence line to the East and West per an old unrecorded survey. Corner is $\pm 1.5'$ West of centerline of North-South road and in fence line to the East and West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- M-4) Set 2 1/2" brass Missaukee County monument on 1/2" Iron in monument box

N 88° E - 63.25 - Set nail in power pole
N 89° W - 56.02 - Set nail in corner fence post
N 37° E - 78.22 - Chiseled hole in top of concrete headwall at the
N 30° N - 78.76 - Chiseled hole in top of concrete headwall at the

center of top
center of top

Peer Group Reviewed and Approve

Date: 12-7-94

J. Dean Geers
J. Dean Geers, Missaukee Co. Representative

Signed by *J. Dean Geers* Date 12/13/94

Surveyor's Michigan License No. 33977