

SURVEY & REMONUMENTATION

LIBER 291 PAGE 405

APR 24 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

959

For corner **COMMISSION**

Missaukee
(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|--------------------------|------------|
| 1. Public Land Survey | T <u>21N</u> R <u>8W</u> | <u>M-9</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous | S _____ T _____ R _____ | _____ |
| Property in Sec. | S _____ T _____ R _____ | _____ |

MISSAUKEE COUNTY MICHIGAN

RECORDED JAN 23 1995 / LA

Paula F. Lare
REGISTER

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, J. Dean Geers, in a field survey on November, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

- M-9) 1837 GLO Section post by John Brink, Deputy Surveyor
Beech 9 S 23 1/2° W 22, Hemlock 14 N 57° W 19
M-9) 1890, 1899, 1919 Beuthien surveys: Post N 41 1/2° E 54.8', Tele pole N 59° W 60.5'
M-9) 1974 McClung LCRC, Liber 1, page 179: Found Iron and monument box in intersection, no witnesses
M-9) 1975 McClung survey, Liber S-1, page 205: Found monument box per Liber 1, page 179
(continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- M-9) Section corner common to Sections 24 & 25, T21N, R8W and Section 19 & 30, T21N, R7W

Found 3/4" pipe recorded in Liber 1, page 179 in monument box in center of intersection. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- M-9) Set 2 1/2" brass Missaukee County monument on existing 1/2" Iron in monument box

N 30° E - 58.27 - Found nail and washer in power pole
S 46° E - 44.82 - Found nail and washer in power pole
S 44° W - 36.44 - Found Pk nail in top of guard post
N 28° W - 64.91 - Found nail and washer in power pole

Peer Group Reviewed and Approved

Date: 11-30-94
J. Dean Geers
J. Dean Geers, Missaukee Co. Representative

Signed by *J. Dean Geers*

Date 12/15/94

Surveyor's Michigan License No. 33977