

MISSAUKIE COUNTY

# 1025

JAN 3 0 1996

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

MISSAUKIE COUNTY MICHIGAN

For corners in  
Missaukee COMMISSION

RECORDED JAN 2 1996 1:15 P

*Register*  
REGISTER

Located In: Corner Code #

1. Public Land Survey	T 23 R 6	D-13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, Daniel E. Schripsema a field survey on August, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
D-13) 1837 GLO post by John Brink, Deputy Surveyor  
Hemlock 10 N82°E 34, Hemlock 10 N13°W 41  
D-13) 1917 Beuthien Notes: Fieldbook #9, pages 50-51  
D-13) 1976 Cavanagh survey, Liber S-1, page 254: set 1/2"x18" steel bar  
D-13) MDOT M-55 file #57-R-1 & 57-R-2, Control Sec. 57022, sheets 18-19: corner is not indicated

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
D-13) South 1/4 corner common to Section 32  
  
Found 1/2" Iron 1' South of centerline M-55, stone house North per Cavanagh survey. This corner is accepted as a careful and faithful reestablishment of the location of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
D-13) Placed Mon. Box and Brass Missaukee County Monument on existing corner with #24617

S05°W	148.60	P.Pole
N10°W	146.45	P.Pole
S37°W	108.54	12" Poplar
N61°E	106.09	6"x4" Post @ Phone Riser

Peer Group Reviewed and Approved  
Date: 1-2-96  
*J. Dean Geers*  
J. Dean Geers, Missaukee Co. Representative

Signed by Daniel E. Schripsema  
Surveyor's Michigan License No. 24617

Date 12-29-95