

SURVEY &
REMONUMENTATION

JAN 6 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

1177

LIBER 314 PAGE 1258

SECTION 36

For corners in

Missaukee
(County)

Located In:

Corner Code #

1. Public Land Survey

T 24N R 7W

L-13

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, J. Dean Geers, in a field survey on June, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- L-13) 1838 GLO Quarter Section Post by John Brink, Deputy Surveyor; Beech 12, Quarter Section Corner
L-13) 1895 County Survey notes of Section 36; Corner was used but no witnesses provided
L-13) 1909 Cavanagh County Surveyor; Set Gas Pipe in concrete; Sugar 20-S15W-80, Sugar 11-S39½E-49; Sugar 20-N55½E-18
L-13) 1972 L. Cavanagh Survey; Liber S-1, Pages 24-27; Set ½" Rerod
L-13) 1981 DNR LCRC, Liber 1, Page 617; Found and accepted 1/2" Rerod set by L. Cavanagh recorded in Liber S-1, Pages 24-27. Replaced with 5/8" x 18" Rerod. N58E-53.66-18" Maple, S09E-34.71-12" Maple, N48W-48.48-6" Maple, N42W-48.7-12" Elm Stump, North-33'-Cedar Post. See dossier for additional notes.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- L-13) Quarter Section Corner common to Section 36, T24N, R7W and Section 1, T23N, R7W; Found 5/8" Rerod as recorded in Liber 1, Page 617. Corner is in centerline East-West road. This corner is accepted as the best evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- L-13) Set Missaukee County Monument on existing Iron
N35W 64.68 12" Maple
N11E 53.16 6" Maple
S08E 34.65 18" Maple
S67W 46.34 30" Maple


Peer Group Reviewed and Approved

Date:

10-15-97
J. Dean Geers, Missaukee Co. Representative

Signed by

Surveyor's Michigan License No.



Date

10-22-97