

MAY 16 1997

COMMISSION

Montmorency County Remonumentation

Liber 00012 Page 0217

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY

(County)

ALBERT TWP.

1. Public Land Survey

Located In:

Corner Code #

T 29N, R 2E

I - 1

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-01-1996 09:43:57

A. PANGAN-MCELROY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, DONALD E MARLATT, in a field survey on MAY 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I - 1 NORTH CORNER COMMON TO SEC'S 2 & 3

CORNER SET BY LEWIS CLASON 3-20-1839

SPR. PINE 6"-S42°E-18, SPR. PINE 4"-S34°W-25

FRANK SMITH NOTES(NO DATE) FOUND OLD STAKE W. OAK 6"-S24°30'W 23.5'-BL. OAK 4"-N49°E-6.9'

G.F. DELAMATER SURVEY 1940. NO CORNER DESCRIPTION.

LEO SMITH SURVEY 1960. CONC. MONUMENT FOUND. LETTER IN FILE.

ACT 74 BY KEN OSTLING L. 1, P. 204, 3-1-78. FOUND CONC. MONUMENT.

DNR SURVEY SEPT. 1977 USED CONC. MONUMENT.

WITNESSES

18"OAK S15°W 24.9'

3" R PINE S68°E 22.3'

SET CEDAR POST

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I - 1 NORTH CORNER COMMON TO SEC'S 2 & 3

FOUND CONC. MONUMENT.

S70°E 8"N.PINE 22.39'

S14°W 22"OAK 25.65'

S.E. COR. OF SEC 34, T30N, R2E 19.6' WEST

NO EVIDENCE OF ORIGINAL CORNER

APPROVED BY
PEER GROUP

JUN 1 06

L.G.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I - 1 NORTH CORNER COMMON TO SEC'S 2 & 3, T29N, R2E.

PLACED REMON. CAP ON CONC. MONUMENT

N45°E 12"N.PINE 11.2'


S70°E 8"N.PINE 22.39'

S25°E 7"N.PINE 17.20'

S14°W 22"OAK 25.65'

WITNESSES MARKED WITH 30 PENNY SPIKES & P.S. TAG #18660

APPROVED BY PEER GROUP JUNE 7, 1996 AS THE BEST AVAILABLE EVIDENCE OF THE RE-ESTABLISHMENT OF THE ORIGINAL CORNER



Signed by

Donald E Marlatt

Date

10/28/96

Surveyor's Michigan License No.

18660