

ì

## LIBER 18782 PG 848

98 228562

## LAND CORNER RECORDATION CERTIFICATE

For comers in	Filing Requirement of Act 74, Mich. P.F	A. 1870
Oakland (County)	Located In: Corner Code # West Bloomfield Township	\$ 7.00 MISCELLANEOUS RECORDING \$ 2.00 REHOWINENTATION
1. Public Land Survey	T2N R9E	3 AUG 98 3:26 P.M. RECEIPT 495A PAID RECORDED - CAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS Compliance with
Property Controlling in Section     Miscellaneous Property in Sec.	T R R JAN 21 Z090  S T R JAN 21 Z090  S T R S T R	ACT 345, P.A. 1990  OF 16-98  OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE
4 Lot No. Record	SECTION To anti-e	Action of Design States at the Hollings
5. Private Claims	in a field survey on May 25 , 1998 o hereby state that us	A B C D E F G H I J K L M  1 2 6 5 4 7 8 9 10 11 12
conformance with regulations and ru United States Department of the Inte	P.A. of 1970, the corner points mentioned in lines 1 and 2 above were less therefore as required in the current manual of survey instructions of sior. Bureau of Land Management or by a decree of a Court of Law an ines 3, 4 and 5 above were in conformance with the rules of the Michill Decree of a Court of Law; established, re-established, monuments.	fthe dd/or 6 18 17 16 15 14 13 igan
NOTE: Not more than 2 corne on this certificate.	ers, all in the same town and range, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
<ul> <li>A. Description of original monument and accessories and/or subsequent restoration:         <ul> <li>1817-GLO Carpenter, D.S.; No post was set</li> <li>1.) 1997-Kolehouse, PS #25854; Unrecorded LCRC – Set a 5/8" x 24" Rebar with a brass cap stamped "Oakland County Remonumentation, PS #25854", East ¼ corner of Section 1, T2N, R8E, Commerce Twp., (M-2).</li> </ul> </li> </ul>		
B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: 1998-Kennedy Surveying, Inc. – Kennedy, PS #17623 - The corner was recovered on a straight line between M-1 and M-3, T2N, R8E, Commerce Township and set at the midpoint between A-1 and A-3, T2N, R9E, West Bloomfield Township. The corner as recovered is 20 feet South of the existing centerline of Flagstaff Drive extending to the East & West, which has a bituminous surface. Also the corner as recovered is 11.72 feet East of the line between West Bloomfield Township and Commerce Township as depicted on the "PENINSULAR PARK" a plat recorded in Liber 24 of plats, on page 13 of Oakland County Records, and is located in Lot 205 of said plat. The East ¼ corner of Section 1, T2N, R8E, Commerce Township (M-2) is located 84.35 feet to the North.		
FIELD MEASURMENTS	BETWEEN	<b>₹</b> (* †
A-2 to A-1 No GLO 2930.93 Ft. (GPS-MEA)	A-2 to M-2 No GLO 84.35 Ft.	E. 1
A-2 to A-3 No GLO 2930.93 Ft. (GPS-MEA)		orjud
A-2 I set a 5/8" x 24" in Due South 8.83' Set M S50°W 66.30' NW corr N03°E 46.33' Set Mag N44°W 52.49' Set Mag	for corner and accessories established to perpetuate location Rod w/2" diarneter brass cap stamped Oakland Coag Nail & Remon Washer East face 30" Oak ner of house #7977 Nail & Remon Washer East face Power Pole Nail & Remon Washer SW face 32" Oak V4 corner of Section 1, T2N, R8E, Commerce Twp., (I	ounty Remonumentation, PS #17623
The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available endered the position of the		
the position of the original	Date _	6-20-98 17025 17025 17025 180 180 180 180 180 180 180 180 180 180
Surveyor's Mickignan License	No. 17673	