UBER 19762 PG 648

107793

PROFESSIONAL

For corners in		LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970			2 PAGE RECORDING UMENTATION 10:42:13 A		ADACE UTO
Oakland (County)	Located In: West Bloomfie	Corner Code # eld Township			ORDED - OA	KLAND COUN	ŧΤΥ
1. Public Land Survey	T <u>2N</u> T T	R9E L-13 R R	Y 8.				
2. Property Controlling in Section3. Miscellaneous Property in Sec.	S T S T S T	R R INFIR Q L R	1	APPROVED O	DUNTY RE	A. 1990 - 3 - 9 9 MONUME!	NTATIO
4. Lot No, Record	led Plat	SECTIO		Register of			
4. Lot No, Record 5. Private Claims		***************************************	1 2 - 3 -	B C D E	F G 1	1 J 3	K L M
I, Huston K. Kennedy in requirements of P.A. 74, Michigan P conformance with regulations and rul United States Department of the International in file Board of Land Surveyors or by a recovered, found as expressed below	A. of 1970, the come es therefore as require tior, Bureau of Land Ma nes 3, 4 and 5 above w Decree of a Court o	or points mentioned in lines 1 are ad in the current manual of surver anagement or by a decree of a C yere in conformance with the ru	nd 2 above were in 5 yinstructions of the Court of Law and/or 6 wies of the Michigan		9	514	12-

Description of original monument and accessories and/or subsequent restoration: 1817-GLO Carpenter, D.S.; Set Post 14" White Oak S50 1/2°E 1.35 Chains; 6" Black Oak N29 1/2°W 80 Links

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

- 1.) 1997-Ward, PS #22445; LCRC for (L-13 West Bloomfield Twp.) L.17466, Pg.796 Set a iron Rod & Cap #22445
- 2.) 1997-Ward, PS #22445; LCRC for (L-1 Farmington Twp.) L.17466, Pg.799 Set a 1/2" Iron Rod in a Monument Box
- 3.) 1962-Oakland County Road Commission Unrecorded Witnesses Fnd "T" Iron
- 4.) 1973-Oakland County Road Commission Unrecorded Witnesses -- Fnd 1/2" Iron Pipe

5.)

on this certificate.

Description of comer evidence found and/or method applied in restoring or reestablishing corner:

1999-Kennedy Surveying, Inc. -- Kennedy, PS #17623 -- Fnd a 1/2" fron Rod w/2" diameter brass cap stamped Oakland County Remonumentation, PS #22445 in a Monument Box located 11.00 feet East of the existing centerline of Ten Hill Road extending to the North & South, which has a bituminous surface. The North 1/2 comer of Section 1, T1N, R9E, Farmington Township L-1) is located 11.72 feet to the West.

1

Witnesses from LCRC #1 were used to recover and verify the location of the found 1/2" Iron Rod w/2" diameter brass cap stamped Oakland County Remonumentation, PS #22445 in a Monument Box

I accepted the found 1/2" Iron Rod w/2" diameter brass cap stamped Oakland County Remonumentation, PS #22445 in a Monument Box as the best evidence of the original comer positon.

HOW THE CORNER WAS SET

"FRANKLIN VALLEY SUBDIVISION", "FRANKLIN VALLEY SUBDIVISION NO. 4", "FRANKLIN VALLEY SUBDIVISION NO. 8" *FRANKLIN OAKS NO. 1*, "FRANKLIN OAKS NO. 2" and "MEADOWLAKE FARMS NO. 1" all depict the South line of Section 36 (township line) but does not indicate the position for L-13.

The corner (L-13) was set at the midpoint between the Southwest corner of Section 36 (K-13) and the Southeast corner of Section 36 (M-13) and line was set using the monumentation as found in Lot 134 of "FRANKLIN VALLEY SUBDIVISION NO. 4". This position was accepted by the Oakland County Peer Group so that North 1/2 comer of Section 1, Town 1 North, Range 9 East, Farmington Township (L-1) could be set. ALLE OF MICHICAL

N85°E 41.59' Fnd Mag Nail & Remon Washer #22445 in South face 8" Apple S40°E 45.77' Fnd Mag Nail & Remon Washer #22445 NE face 4" Pine
S85°W 72.88' Fnd Mag Nail & Remon Washer #22445 North face 18" Cherry
N75°W 78.53' Fnd Mag Nail & Remon Washer #22445 NE face 18" Maple
West 11.72' North ½ corner of Section 1, T1N, R9E, Farmington Township (L-1)

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

the position of the original corner.

رمع ۱۷)	∕ ∧	•
Signed by: Austil	_ }	Date 3-10-99
Surveyor's Michigan License No.	U1623	,