LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

		2
ror	corners	าท

For corners in							
Ontonagon (County)	Located In:	Corner Code #					
1. Public Land Survey	T R T R T R T R T R T R T R T R T R T R						
2. Property Controlling in Section	S 33 T 52N R 37W S T R S 33 T 52N R 37W	8 (GCDB 320140)					
3. Miscellaneous Property in Sec.	S T R S T R	(GCDB 300120)	Registe	er of Deeds	Stamp & File	Number	
•	corded Plat		3 9 0				
5. Private Claims			1 7 7	D E	F G H	I J K	LM
			2 - 6-	╼┇╼┼╌	i——	├─ ネ─┼─	1-1
ı, Stephan J. Szyszkoski , in	a field survey on 09.	/15/15 do hereby state	3			 -	+
	74, Michigan P.A. of 1970, the corner p	,	4 - 7-	 ∮	3	11	12-
above were in conformance with re	regulations and rules therefore as require	ed in the current manual of survey	5	- 			\sqcup
	Department of the Interior, Bureau of La			-17-1	615	14	13_
a Court of Law and /or that the co	orner points mentioned in lines 3, 4 and	5 above were in conformance with	7				
the rules of the Michigan Board	of Land Surveyors or by a Decree	of a Court of Law; established,	8 -19-	202			1
re-established, monumented, recover	red, found as expressed below:		9 1				"
			10 30				\vdash
NOTE: Not more than 2 corne	ers, all in the same town and range,	may be recorded			827	26	25— 1
on this certificate.	-	-	11				+
			12 31	-323	334	35	36
A Description of original and			13				لــــــــــــــــــــــــــــــــــــــ
A. Description of original mo	onument and accessories and/or s	subsequent restoration:			OF	IGNIC	
					(A)	11	
				# *	STEPHA	N	
(8-Sec. 33) Center-Wes	st 1/16 corner, Section 3	3. Not previously mon	umented.	12/	SZYSZKO		1
		<u> </u>		3 [1	LAND		
				1	SURVEY	OR	70
					No. 33986	5	
					AND	TRY	
(10-Sec. 33) South 1/1	16 corner between Sections	22 and 22 Web			AND :		
2/1	Neguccii pectitiii	5 52 and 55. Not prev	TOUSTA M	onumente	a.	-	
B. Description of corner evid	dence found and/or method appli	ed in restoring or reestablish	ing comer:				

(8-Sec. 33) Established the position for the corner midway and on a straight line between Quarter corner 1322.11' west and the Center of Section 33 1322.11' east.

(10-Sec. 33) Established the position for the corner midway and on the Section line between Section corner 1310.34' south and Quarter corner 1310.34' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 4" Sugar N17°W 3.7' mrkd "1/16S BT" 6" Sugar N41°E 11.3' do 9" Sugar S29°E 17.65' do 7" Sugar S54°W 9.5' do Set sq'd cedar post adjacent. E= 7846611.318 N= 232643.631	(10) Set 1"IDx28" I.pipe with Set measuring nail with MDNR 13" Sugar N24°E 20.0' 6" Sugar S50°E 7.3' 9" Sugar S02°E 10.35' 6" Sugar N87°W 27.0' Set sq'd cedar post adjacent E= 7846205.159 N= 232249.5!	tag in the side of: mrkd "1/16S BT" do do do do
---	--	---

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0503: N= 233736.672 m. E= 7856830.965 m.

	which!	Date	09/23/2015	
Surveyor's Michigan License No.	33986			