

1210
1996 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Presque Isle
(County)

Located in:

Corner Code #

1. Public Land Survey

T^{34N} R^{5E} G-8
T R
T R
T R
T R
S T R
S T R
S T R
S T R

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

LIBER 319 PAGE 123

PRESQUE ISLE COUNTY
RECORDED

96 JUL 12 AM 11:40

Jane M. Lamb
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, James A. Beck, in a field survey on Mar 11, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-8

G.L.O. 1856
Alfred Millerd

"Set qr. Section post"
Elm 10 S57°W 24
Hemlock 10 N 38°E 20

Sep. 25, 1978
P.A. 74 Recordation
by Delmer Porter
Reg. No. 15410
1/2" rod & cap in mon. box
Witnesses:
N 52°E 38.93' Stump
S 48°E 45.27' P. Pole
S 79°W 38.04' Fe. Post

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-8

1996 Remonumentation
by James A. Beck

found 1/2 " iron rod and 15410 cap
in monument box at center of tar surface road
4' + or - Southerly of fence Westerly extended

witnesses:
N 52°E 38.93' stump
S 48°E 45.22' 15410 tag in power pole
S 79°W 38.00' 15410 tag in fence post

Ratified by Peer Group

in accordance with P.A. 345

Chairman *Delmer Porter*

Date 5/22/96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-8

1996 Remonumentation
by James A. Beck

1/2 " iron rod and 15410 cap
in monument box at center of tar surface road
4' + or - Southerly of fence Westerly extended

witnesses:
N 52°E 38.93' stump
S 48°E 45.22' 15410 tag in power pole
S 79°W 38.00' 15410 tag in fence post
S 33°W 53.91' 21559 tag in 7" Elm
N 20°W 53.27' 21559 tag in 13" Elm



Signed by *James A. Beck*

Date June 17, 1996

Surveyor's Michigan License No. 21559