

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Liber 6 Page 256

For corners in

Saginaw

(County)

Located In:

Corner Code ##

SURVEY &

1. Public Land **REMONUMENTATION** NR 3 E. M-4

T R

T R

APR 24 1995

T R

T R

2. Property Controlling S T R

in Section COMMISSION R

3. Miscellaneous S T R

Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

MICHIGAN
REGISTER OF DEEDS
SAGINAW COUNTY MICH

DEC 27 9 15 AM '94

RECORDED & FILED

Register of Deeds Stamp & File Number

I, Ronald C. Prevost, in a field survey on December 6, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-4 Post by Joseph Wampler in 1822.
Beech 13" S.80°W. 9 1/2 Lks.
Beech 9" N.30°E. 8 1/2 Lks.
LCRC Hammond 1978 P.K. Nail in Bridge Deck/L.4, P.165
LCRC Prevost 1985 found P.K. set RR spike in its place/L.6, P.10
Note: Witness on both LCRC the same

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-4 Found RR Spike & Recorded Witnesses
South 16.80 W 1/4 corner Sec 7, T.12 N.-R.4 E. (16.78)
NW 31.35 N end guard rail post (31.57 Nail & Cap Guard Post)

Is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-4 Replaced RR spike with 5/8" Rerod 2 1/2" Saginaw Co. Bronze Cap & Mon. Box
South 16.78 corner A-4, T.12 N.-R.4 E.
S.80°W. 25.35 N edge gasline marker
N.35°E. 20.0 S edge RR track support for bridge
S.30°W. 31.57 nail & cap in end guard rail post



Signed by

Ronald C. Prevost

Date

12-15-94

Surveyor's Michigan License No.

24612