

REMONUMENTATION

NOV 21 1997

COMMISSION

LIBER

2 PAGE 144

REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

97 SEP -9 AM 8:58

LIBER NO. 2 PAGE NO. 144
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac
(County)

Located in:

Corner Code #

1. Public Land Survey

T10N R13E

G - 1

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, John A Millettics, in a field survey on June 12, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G - 1

GLO Notes

Intersect 29 Links West

Birch 16, S13W 30

Birch 7, S45½E 38

APPROVED PEER BOARD MEETING

Aug 18, 1997 Jm

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G - 1

Found Monu Box - removed by Sanilac Co. Road Comm. during reconstruction of road, REPLACED using Act 74 recording Liber 1 Page 380

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G - 1

NW Corner Section 3 T10N-R13E

Monu Box Set with iron & cap

East 20.05 to the SE cor Section 32 T11N-R13E Monu Box

N45°W 83.70 to SE Cor of a Bldg

S45°W 69.00 to a nail in a Power Pole

N45°E 82.36 to a nail in a Power Pole

S45°E 61.47 to a Riser Box

East 2639.06 to the N 1/4 Cor Section 3

Signed by John A Millettics

Surveyor's Michigan License No. 25859

Date Aug 11, 1997

