

JAN 22 2001

LIBER 3 PAGE 53

RECEIVED FOR RECORD

00 NOV 29 AM 11:11

LIBER NO. 3 PAGE NO. 53
MICHELE VANORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
2000 REMONUMENTATION PROGRAM

For corners in

Sanilac
(County)

Located in:

Corner Code #

1. Public Land Survey

T11NR16E	F - 1
T R	
T R	
T R	
T R	
T R	
T R	
T R	
T R	
T R	

2. Property Controlling in Section

S

3. Miscellaneous Property in Sec.

S

S

S

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		6			5		4		3		2	
5													
6	8		7			6		5		4		3	
7													
8	9		8			7		6		5		4	
9													
10	10		9			8		7		6		5	
11													
12	11		10			9		8		7		6	
13													

John A Millettics, in a field survey on May 1, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or at the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, covered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO Notes

None

Act 132 - None

Old Survey Liber - None

State Highway Right of Way Book Page 73

L.C.R.C Forms - None

Unrecorded surveys - Millettics Oct 1997 - Millettics May 1998

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F - 1

N 1/4 Corner Section 4 T11N-R16E

Found no evidence of corner at site - State Highway Department removed corner during construction

West 2638.57 feet to the NW Corner Section 4

East 2650.92 feet to the NE Corner Section 4

Accepted as best evidence

APPROVED PEER BOARD
MEETING Nov 25, 2000

gm

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F - 1

N 1/4 Corner Section 4 T11N-R16E

1/2" Iron bar with cap in concrete

North 1.30 feet to the centerline of M - 46

West 24.00 feet to the S 1/4 Corner Section 33

N20°W 63.80 feet to a barbed cable sign post

N10°W 56.50 feet to a nail in a Power Pole

S05°W 58.50 feet to a nail in a Power Pole

N60°E 109.53 feet to a nail in a 24" Maple

West 2638.57 feet to the NW Corner Section 4

East 2650.92 feet to the NE Corner Section 4

Witnessed by John A Millettics

Surveyor's Michigan License No. 25859

Date Nov 15, 2000