

JAN 22 2001

LIBER 3 PAGE 39

2000 Remonumentation Program

RECEIVED FOR RECORD

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

00 NOV 27 AM 8:56

LIBER NO. 3 PAGE NO. 39  
MICHELE VANNORMAN  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

For corners in

Sanilac Located in: Corner Code #  
(County)

1. Public Land Survey T12N R15E J - 13  
T R  
T R  
T R

2. Property Controlling S T R  
in Section S T R

3. Miscellaneous S T R  
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

2000

I, John A Millettics, in a field survey on May 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4		3		2		1
3													
4	7			8			9		10		11		12
5													
6	18			17			16		15		14		13
7													
8	19			20			21		22		23		24
9													
10	30			29			28		27		26		25
11													
12	31			32			33		34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Hemlock 8" N20°W 4 1/2 Links

Hemlock 10" N40 1/2°E 22 Links

Act 132 - Liber 2 Page 451 I.E. Chope 1974, Liber 4 Page 157 Kay Eng

Liber 4 Page 738 Sanilac Land Survey

L.C.R.C. - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J - 13

S 1/4 Corner Section 35 T12N-R15E

Found 1/2" Iron in Monu. Box

West 2648.30 feet to the SW Corner Section 35

East 2648.27 feet to the SE Corner Section 35

Accepted as best evidence



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J - 13

S 1/4 Corner Section 35 T12N-R15E

1/2" Iron with cap in Monu Box

S10°W 18.00 feet to a nail in a Power Pole

S60°E 39.85 feet to a nail in a 3" Maple

North 64.70 feet to a nail in a Power Pole

S10°W 42.95 feet to the NE Corner of a House

West 6.12 feet to a 1/2" Iron in a Monu. Box

West 2648.30 feet to the SW Corner Section 35

East 2648.27 feet to the SE Corner Section 35

APPROVED PEER BOARD  
MEETING NOV 25 2000

*gm*

Signed by John A Millettics

Date Nov 15, 2000

Surveyor's Michigan License No. 25859