

SCHOOLCRAFT COUNTY
PEER GROUP APPROVED

DATE Dec. 7, 1995 LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

JAN 8 0 1996

COMMISSIONER

For corners in

Schoolcraft
(County)

Located In:

Corner Code #

1. Public Land Survey T 42N R 15W E12
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

Received & Filed this 26 day of
Dec. 1995 at 2:33 p M
Sigrid I. Hedberg
Schoolcraft Co. Reg. of Deeds

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Thomas P.O'Brien, in a field survey on Oct. 19, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E12 (East 1/4 Corner, Sec.32)
Sept 19, 1850 Algernon Merryweather set 1/4 post
Birch 12 in n87W 27 links
Sugar 8 in East 11 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Nov.28, 1979 Thomas P.O'Brien, RLS recovered R/R spike set by Beryl M.Jones, RLS.
Spike is in centerline of county road and in line with fences East & West.
Occupation lines match this corner position. Corner recorded in Liber 1, P219.

Oct.19, 1994 Thomas P.O'Brien, PS recovered R/R spike below blacktop and in same
position as in Nov.28, 1979 as verified by distance to S.E. Corner of Sec.32.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E12 Iron bar 6/21274 cap set in monument box.

Witnesses:

30" White Pine N50°W 55.70'
6" White Pine N69°E 53.50'
Power Pole S10°E 87.70'
8" Red Pine S38°W 49.15'
Face of gate post N87°W 67.30'



Signed by Thomas P. O'Brien Date Dec. 26, 1995

Surveyor's Michigan License No. 21274