## SURVEY & REMONUMENTATION

## REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

RECORDED -

MAY 28 1997

Filing Requirement of Act 74, Mich. P.A. 1970 96 AUG 16 PM 2: 38

COMMISSION	riilig Keq	fullement of Act 74, which P.A. T	370 30 HOO TO THE CO
For corners in	l a safad las	C C-d- # 1	REGISTER OF DEEDS
Shiawassee (County)	Located In:	Corner Code #	Laye Studde
			SHIAWASSEE COUNTY MICH.
Public Land Survey	T 7N- R 1E T 6N R 1E T R	D-13 (SW 32) D-01 (NW 5)	
Property Controlling S     in Section S			
3. Miscellaneous S Property in Sec. S	T R T R		Register of Deeds Stamp & File Number
4. Lot No, Recorder 5. Private Claims	d Plat		- ABCDEFGHIJK
o. Titale oldino	· <del></del>	,	2 6 5 4 3 2
I, Norman C. Caldwell	in a field current on		3
do hereby certify that under requirem	ents of P.A. 74, Michigan P	.A. of 1970, the corner points mentioned	4 7 8 9 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		and rules therefore as required in the artment of the Interior, Bureau of Land	6 18 17 16 15 14
		rner points mentioned in lines 3, 4 and 5 do f Land Surveyors or by a Decree of a	7
Court of Law; established, re-est		re-monumented, recovered, found as	8 19 20 21 22 22 23
expressed below:	1	-	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			10 30 29 28 27 26 3
on this certificate.			12 31 32 33 34 35
A. Description of original mont	ument and accessories	and/or subsequent restoration:	13
D-13 Township Corner, T6	6 7N, RIE		MICH
Post placed by Robert Intersected Meridian (4181.76') North of p	n at 10,00 chains	, 1831, NO REFERENCES MARKED. (660'), 3 chains (198') west	of creek, and 63.36 chains
		dated 1916 in Book 45 at page 48 Line 3.165 chains (208.89') eas	of the Shiawassee County Drain t of the Township Corner
1974 recorded in Libe "signal", 3' South of 1529' north of the E 33.00' 1" Pipe, N 62	er 1 at page 210 of of the physical cer last 1/4 Corner of 8 E 58.7' 10" Black W	Shiawassee County records drove sterline of Bibbard Road, 1330.	
D-13 Township Corner, T6	5 7N, RIE		
the record. Approximagnetic attraction. this area. The 12"	mately 3" below the Upon removal of th anchor post has been	nd excavated in a search for the pavement surface we found a 2 <sup>a</sup> : he pipe and lode stone there was a removed, however the calculation th of the Township Line and 23'	lode stone with significant no magnetic "signal" left in . ons with Brewers bearing and
The Michigan Meridia	n passes 8.50' West	of the Brewer pipe, and subtrac	ting 8' from 23' leaves 15'

(SEE SECTION "B" ON BACK)

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

## Township Corner, T6 & 7N, R1E

Placed a standard Harrison monument in a monument box 3' south of the physical centerium of the Standard Road at the intersection of the Michigan Meridian and the Township Line extension from the Standard Road at the intersection of the Dipe by Brewer. LE OF MICH

(nearly 1 rod) which would appear to support the statement that the subject post 1s an "anchor post" to the former fence corner.

#12018 Tag in 14" Walnut #24832 Tag in Power Pole N 60 E 66.16' S 65 E 91.16' N 65 E S 15 E #25832 Tag in Power Pole 3/4" pipe (Brewer) Center of concrete bridge 99.14' 33.831

619,35' Standard Corner of 32 & 33

Iron in monument box/Meridian & Hibbard roads East 1321.71' West

CMM Signed by

Surveyor's Michigan License No.

Remonumentation

ADAPTED FOR WORD PROCESSI

NORMAN C.

CALDWELL

PROFESSIONAL

SURVEYOR

No.

12018

OFESSION

Peer Review Group