

**Ottawa County Remonumentation
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in
Ottawa
(County)

Located In: _____ Corner Code # _____

- | | | |
|------------------------------------|--------------------------|-------------------------|
| 1. Public Land Survey | T <u>5N</u> R <u>14W</u> | <u>J-13 (S 1/4, 35)</u> |
| | T _____ R _____ | <u>Zeeland Twp.</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

RECORDED

96 DEC 17 AM 10:42

Phyllis Callman
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, John C. Bueche, in a field survey on October 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

J-13 GLO	Peck, 1893	CP
Lucuis Lyon, DS, 1831	Set stake & stone midway on true line	Found cor.
Set HMP	2644.5'	S 88° 16' 46" E 2651.58' to SE
Beech 14 N 59 E 36		S 89° 04' 59" E 2642.62' to SW
Sugar 5 N 54 W 38		No wit. given, no date

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-13 Did not find anything
Set corner 1/2 way and on line as per County survey records of 1893
Meas. 5293.36', 2646.68' - 2646.68'
CP Co. did not say waht was found & had no wit.
Corner is on field division E-W, N-S

And is accepted as a careful and faithful perpetuation of the position of the original corner.

P.A. 345 OTTAWA COUNTY
PEER APPROVED 11-11-96

M.O.P.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-13 Set Ottawa Co. Mon. (3/4" x 24" pin with cap)
Nail & Ottawa Co. Remon. Tag in E side PP N 30° W 9.53'
Nail & Ottawa Co. Remon. Tag in W side 12" Oak S 60° E 78.88'
Nail & Ottawa Co. Remon. Tag in W side 10" Hickory S 30° E 60.67'
Nail & Ottawa Co. Remon. Tag in W side 8" Oak S 10° W 38.89'
On field division N; on field division E-W
West edge of woods South, West 5'±
Power line West, North 8'±; Power line East, South 18'±

\$ 9.00 CORNER
\$ 1.00 PHOTO



Signed by John C. Bueche
John C. Bueche, P.S.
Surveyor's Michigan License No. 13027

Date 11-7-96