FEB 0 8 1999

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING MELD ON

Surveyor's Michigan License No.__

33985

SECTION

E.R. REED

BRANCH COUNTY REMONUMATION PROGRAM LAND CORNER RECORDATION CERTIFICATE OF MICHIGAN Filing Requirement of Act 74, Mich. P.A. 1970 Branch County

Recorded For corners in 12-07-1998 13:52:49 BRANCH COUNTY Located In: Corner Code # Linda Lee Morrison-Mathews **BUTLER TWP** REGISTER OF DEEDS 1. Public Land Survey T<u>5S</u> R<u>5W</u> C-3 Т R 2. Property Controlling Т in Section 3. Miscellaneous Property in Sec. _ , Recorded Plat __ 5. Private Claims 2 .3 in a field survey on AUGUST 28 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of 6 survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above 7 were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. QUARTER CORNER COMMON TO SECTIONS 3 & 10 A. Description of original monument and accessories and/or subsequent restoration: 1825: R. CLARK JR. - D.S. - CORNER SET 1878: M. KNOWLES. CO. SURVEYOR- FD STONE 1911: W.W. COX- DEPT CO. SURVEYOR- FD STONE WELL PLANTED PLACED VITRIFIED TILE AROUND 1977: E R REED- CO SURVEYOR- FD POINTED STONE 30" DEEP- SET ½ x 30 IRON OVER STONE, RECORDED IN LCRC #0206 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 1" IRON PIPE FITTING WITNESS OF MSHD AND LCRC OF WILLIAM ROGERS Description of monument for corner and accessories established to perpetuate locating the position of the corner: JURFA SET ½" X 18" REBAR IRON WITH REMON CAP IN CI-MONUMENT BOX FLUSH WITH ROAD SURFACE 10181819 38" OAK S 45 W 37.7' TO CENTER 38' OAK S 61 W 47.6' TO CENTER **EDWARD** 44" STUMP NORTH 32.2 W. REED 38" OAK S 83 W 91.4' TO CENTER LAND C/L OF HERRICKSVILLE ROAD 0.8 FEET NORTH SURVEYOR NO. 33988 AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION WED LAND SU OF THE POSITION OF THE ORIGINAL CORNER. Signed by Date NOV. 4, 1998 EDWARD W, REED