

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 3 E. . .

. . . . . Chippewa . . . . . COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 11, 12, 13, 14 .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . . . .

WITNESSES TO CORNER 10" Cedar S 23° E 59½ links . . . . .

8" Cedar S 37° W 57 links . . . . .

Boulder 5' high East 27 links . . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Replaced Section Corner from one White Pine and one Cedar stp. (B.T.'s),  
poor condition.

According to Government Notes, Meander Corner West should be 8.00 chs.  
Actually is 3.06 chs.

Corner placed and witnessed February 21, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 3/19/56  
REGISTERED LAND SURVEYOR