DEC 07 1994

expressed below:

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	SION Filing Requir	Filing Requirement of Act 74, Mich. P.A. 1970 RECORDED		
Clinton	Located In:	Corner Code ≠	Hand Computed	
Public Land Survey	T <u>5N</u> R <u>2W</u> T R T R T R	G-13(G-9)	HAR 15 3 38 PM '94 REGISTER OF DEEDS CLINTON COUNTY, HICH. Carol Wooley.	
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R		LIBER 4, PAGE 19 Register of Deeds Stamp & File Number	
	Recorded Plat		A B C D E F G H I J K L M	
do hereby certify that under re in lines 1 and 2 above were	p., sn a field survey onOcceptions of P.A. 74, Michigan P.A. in conformance with regulations attructions of the United States Department.	of 1970, the corner points mer nd-rules-therefore as required	ntioned d in the	

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

- A. Description of original monument and accessories and/or subsequent restoration:
 - G-9 Original survey by Harvey Parke D.S., in 1827, survey of Section 28 by Chas E. Hollister, County Surveyor in October, 1880 indicates he found old bearing tree. Corner recorded by John A. Sellek in Liber 2, page 292.
 - G-13 Original survey by Harvey Parke D.S., in 1827. A.N. Bateman used corner G-1 (Ingham County) for subdivisions South - Found original subdivision monuments and set this corner from closing distance in the late 1960's. Corner recorded in Liber 2, page 751.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Dewitt Township

- G-9 Retraced North line of Section 28, T8N, R2W, I believe the existing 3/4" rod in monument box represents the intersection of the E-W section line and the Centerline of Highway US-27. The Section Corner is 10.84 ft. West from the existing monument.
- G-13 Existing boatspike in monument box is the correct location for this corner and is herein verified as said corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9 (Witness corner) 3/4" rod in monument box ' G-13 (SE corner Section 33) Boatspike in monument box

Corner is -West- 10.84'

N & T N. side power pole -\$69°W- 74.62'

N & T N. side power pole $-N79^{\circ}W-$ 147.40 $^{\circ}$

N & T S. side power pole -\$60°E- 91.80'

N & T N. side guy pole -\$53°E- 90.18'

Boatspike in monument box -West- 2.64'

12" rod in monument box -S65°W- 3.50'

N & T #30897 SE side power pole -N63°E- 53.66'

N & T NE side telephone pole -S50°E- 56.04'

N & T SW side telephone pole -N37°W- 67.40'

N & T NW side power pole -S47°W- 64.991

Surveyor's Michigan License No.

APPROVED BY
CLINTON COUNTY PEER GROUGIE November 24, 1993 DATED .

S. PIERSON

FORM APPROVED BY MICHIGAN STREE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1915 REVISED JAN. 1983

人员的现在分词 计

REVISED JAN

7.200.000 (VEC)

13039