

DEC 18 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
1995 NOV 21 AM 11:26

For corners in
Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey T 39N R 29W
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R

F-1
F-3

REGISTERED DEEDS
MICHIGAN COUNTY
SCHOOL DISTRICT

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5		4		3		2				
3												
4	7	8		9		10		11		12		
5												
6	18	17		16		15		14		13		
7												
8	19	20		21		22		23		24		
9												
10	30	29		28		27		26		25		
11												
12	31	32		33		34		35		36		
13												

I, Robert F. Perkins, in a field survey on Oct. 11, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-1 North $\frac{1}{4}$ Corner, Section 4
Post J. Mullett, D.S. 1848
Original Bearing Trees
Cedar 8" N71°E 17 Lks.
Cedar 4" N10°W 24 Lks.

F-3 South $\frac{1}{4}$ Corner, Section 5
Post J. Mullett, D.S. 1849
Original Bearing Trees
Cedar 4" N17°E 12 Lks.
Hemlock 6" S20°E 14 Lks.

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON

11-26-95
R.F.P.

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-1 No Evidence of Original Corner or Accessories Found.
Found 1" Sq. Bolt buried 5" in Road $\frac{1}{2}$ at Old East-West Fences (Corner Recorded as F-13 T40N-R29W in 1984).
Corner Researched in 1994.

F-3 No Evidence of Original Corner or Accessories Found.
City of Norway Land Record (Sh. 11-H) indicates Iron Pin in Concrete at Old Fence Corner.
Corner Researched in 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-1 Accepted above described Corner.

New Witnesses

Set 3" Stamped D.C. Remon. W.C.,
N80°W (M.B.) 20.00'
Set 3" Stamped D.C. Remon. W.C.,
S80°E (M.B.) 20.00'
Cedar 4" S66°W (M.B.) 55.00'
X Cut on 4' Boulder N68°E (M.B.) 33.22'
Set Carsonite Stake at Witness Corners

F-4 Found and Accepted above described Monument.

New Witnesses

X Cut in 1' Boulder N13°W (M.B.) 8.52'
X Cut in 3' Boulder N74°W (M.B.) 71.75'
X Cut in 2' Boulder S76°E (M.B.) 18.31'
Apple 8" S35°E (M.B.) 35.46'
Placed Carsonite Marker 1.83 Feet North of Corner.

Signed by Robert F. Perkins

Date Nov. 7, 1995

Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 1978
REVISED JAN. 1983

