

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 NR. 28 W.

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 29, 30, 31, 32

DESCRIPTION OF CORNER MONUMENT 1 1/2" Iron Pipe

WITNESSES TO CORNER 14" Hemlock - N 82 W - 34 Links

12" Hemlock - N 10 W - 46 Links

10" Hemlock - N 79 E - 62 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was pointed out to me by H. S. Peterson, District Forester,
of Iron Mountain. One original B.T. still in place, in poor condition. Corner
had been previously perpetuated by unknown Surveyor.

Corner was witnessed June 7, 1951.

SURVEYORS SEAL

SIGNED Sean C. Peterson DATE 6/15/51
REGISTERED LAND SURVEYOR